GEOTECHNICAL INVESTIGATION

Yerba Buena Road Distress Ventura County Public Works Agency Ventura County, California



Prepared for: Mr. Daniel Espinoza Roads and Transportation Department VENTURA COUNTY PUBLIC WORKS AGENCY 800 South Victoria Avenue #1600 Ventura, California 93009

April 2025



646 University Ave • Los Gatos, California 950302• (408) 354-5542 Dogtown Road • San Andreas, California 95249 • (209) 736-4252 699 Hampshire Road, Suite 102 • Thousand Oaks, California 91361 • (805) 370-8710



April 29, 2025 SC6164

Mr. Daniel Espinoza Roads and Transportation Department VENTURA COUNTY PUBLIC WORKS AGENCY 800 South Victoria Avenue #1600 Ventura, California 93009

SUBJECT:Geotechnical InvestigationRE:Yerba Buena Road DistressVentura County, California

Dear Mr. Espinoza:

Cotton, Shires and Associates, Inc. (CSA) is pleased to present **Ventura County Public Works Agency (County)** with this geotechnical investigation for the proposed roadway distress repairs along Yerba Buena Road in unincorporated Ventura County, California. Geotechnical engineering services for this project were provided in accordance with our proposal dated October 4. 2024, and authorized under Agreement No. AE25-018 (County Project No. P6050666) dated October 21, 2024. We prepared a previous draft report dated April 1, 2025. CSA subsequently received review comments on the draft report from the County, and our responses and comment resolutions are included in this final report.

In this report, we characterize the geotechnical conditions underlying the four (4) sites, or mile post (MP) locations, along Yerba Buena Road to develop geotechnical recommendations and design criteria for repair alternatives.

We appreciate the opportunity to be of continued service to you on this project. If you have any questions regarding this report, please feel free to contact us.

Sincerely,

Matthew J. Janousek Principal Geotechnical Engineer PE 73401, GE 3005; exp. 12-31-2026

Edward Porgracz-Bartha Supervising Engineering Geologist PG 7673, CEG 2370; exp. 11-30-2025

COTTON, SHIRES AND ASSOCIATES, INC.



Northern California Office 646 University Avenue Los Gatos, CA 95032-4416 (408) 354-5542 Central California Office 6417 Dogtown Road San Andreas, CA 95249-9640 (209) 736-4252 Southern California Office 699 Hampshire Road, Suite 102 Thousand Oaks, CA 91361-2352 (805) 370-1870

www.cottonshires.com

GEOTECHNICAL INVESTIGATION YERBA BUENA ROAD DISTRESS Ventura County, California

Table of Contents

1.0	INT	ROD	UCTION	1
	1.1	P	roject Description	1
	1.2	P	urpose and Scope of Work	1
		1.2.1	Research and Review of Available Data	2
		1.2.2	Pre-Field Planning and Coordination	2
		1.2.3	Geologic Mapping	2
		1.2.4	Subsurface Exploration	2
		1.2.5	Geotechnical Laboratory Testing	3
		1.2.6	Geotechnical Evaluation and Reporting	3
2.0	SIT	E CO	NDITIONS	3
	2.1	St	urface Conditions	3
		2.1.1	Regional Surface Conditions	3
		2.1.2	Site-Specific Roadway and Slope Distress	5
	2.2	G	eologic Setting	7
		2.2.1	Regional Geology	7
		2.2.2	Geologic Structure	8
	2.3	St	ubsurface Conditions	8
		2.3.1	Artificial Fill (Af)	9
		2.3.2	Natural Soil (Qs) / Colluvium (Qc)	9
		2.3.3	Landslide Deposits (Qls)	9
		2.3.4	Lower Topanga Formation (Ttlc)	9
	2.4	G	roundwater Conditions	9
3.0	SEI	SMIC	ITY1	0
	3.1	Se	eismic Setting and Nearby Fault Sources1	0
	3.2	20	022 CBC/ASCE/SEI 7-16 Seismic Design Criteria1	0
	3.3	Р	eak Ground Accelerations1	2
4.0	SEI	SMIC	GEOHAZARDS1	2
	4.1	Fa	aulting and Ground Rupture Potential1	2

	4.2	Ts	sunami and Seiche Hazard	12
	4.3	Li	quefaction Potential and Related Settlement	12
	4.4	La	andslide and Slope Instability	13
5.0	CON	ICLU	JSIONS AND RECOMMENDATIONS	14
	5.1	А	lternative Repair Options	14
	5.	.1.1	Do Nothing Option	14
	5.	.1.2	Soil Nail Walls	14
	5.	.1.3	H-Pile Wall	14
	5.	.1.4	Repair of Upslope Areas	15
	5.2	Si	te Development and Grading	15
	5.	.2.1	Site Preparation	15
	5.	.2.2	Excavation Considerations	16
	5.	.2.3	Temporary Excavations	16
	5.	.2.4	Subgrade Preparation	16
	5.	.2.5	Fill Material Selection	17
	5.	.2.5.2	l Subgrade Fill	17
	5.	.2.5.2	2 Aggregate and Miscellaneous Base	17
	5.	.2.5.3	3Use of Onsite Materials	17
	5.	.2.5.4	Imported Fill	17
	5.	.2.6	Fill Placement	17
	5.	.2.7	Compaction Requirements	17
	5.	.2.8	Import Fill	
	5.	.2.9	Cut/Fill Slope Design	
	5.3	Η	-Pile Wall Design	
	5.	.3.1	Drilled Shaft Foundations	
	5.	.3.2	CIDH Piles	19
	5.	.3.3	CIDH Installation Considerations	20
	5.	.3.4	Lagging	20
	5.4	R	eplacement of Existing Asphalt Concrete Pavement	21
	5.5	G	eneral Corrosivity Considerations	21
	5.6	Te	echnical Review	22
	5.7	Ea	arthwork Construction Inspection Testing	22

6.0	INVESTIGATION LIMITATIONS	.22
7.0	REFERENCES	.23

TABLES

<u>Page</u>

Table 1. ASCE/SEI 7-16 Seismic Design Criteria	11
Table 2. Peak Ground Acceleration Based on USGS Unified Hazard Tool	12
Table 3. Summary of CIDH Allowable Axial Design Values	19
Table 4. Summary of CIDH Allowable Lateral Design Values	19
Table 5. Summary of Corrosivity Test Results	21

FIGURES

<u>Figure No.</u>

Site Vicinity Map	1
Regional Geologic Map	2
Landslide Inventory Map	3a and 3b
Geologic Map and Cross-Section for MP 0.93	4a and 4b
Geologic Map and Cross-Section for MP 1.94	5a and 5b
Geologic Map and Cross-Section for MP 2.61	6a and 6b
Geologic Map and Cross-Section for MP 2.96	7a and 7b

APPENDICES

Appendix A – Field Exploration Appendix B – Laboratory Testing Appendix C – Seismic Design Parameters

GEOTECHNICAL INVESTIGATION YERBA BUENA ROAD DISTRESS Ventura County, California

1.0 INTRODUCTION

Cotton, Shires and Associates, Inc. (CSA) is pleased to present **Ventura County Public Works Agency (County)** with this geotechnical investigation for the proposed Yerba Buena Road Distress project in southeastern Ventura County, California.

1.1 <u>Project Description</u>

The project consists of geotechnical evaluation of the observed pavement distress, i.e. tension and/or extension cracks and/or roadway settlement, at four (4) mile post (MP) locations along Yerba Buena Road, along with the presentation of pavement and slope repair alternatives. Based on our site reconnaissance and discussions with County staff, we understand that the proposed pavement and slope repairs will need to be evaluated at mile posts (MP) 0.93, 1.94, 2.61 and 2.96 along Yerba Buena Road.

We understand that other geotechnical studies conducted along Yerba Buena Road, for similar County road conditions, have included slope repair alternatives such as fill slope restoration, h-piles and lagging, and soil nail retaining walls.

During our September 26, 2024, site visit with you, we observed distressed pavement at each site, possible downslope failures or slumps at MP 1.94 and 2.96, tension cracks along the top of the descending slopes, and possible mapped landslides upslope and downslope of MP 1.94, all of which may impact the level of effort required to evaluate the suitability of slope repair alternatives at each site. General project site limits are delineated on Figure 1 – Site Vicinity Map.

1.2 Purpose and Scope of Work

The purpose of our investigation was to explore and generally characterize the earth materials at each of the four (4) mile post (MP) locations, evaluate potential hazards including erosion, settlement, slope creep, landslides and seismic geohazards, and to develop preliminary geotechnical design recommendations and design criteria for subsequent design concept(s) and roadway repair plans (by others). A summary of the work performed is outlined below. **1.2.1 Research and Review of Available Data** – We researched, reviewed and compiled data from available historic aerial photographs and published and readily available documents to gain background data regarding previous site uses (if any) and geotechnical conditions.

1.2.2 Pre-Field Planning and Coordination – Prior to subsurface exploration at the four (4) mile post locations, we performed a site reconnaissance to locate and mark the exploration locations. Subsequently we contacted Underground Service Alert (USA) for underground utility clearance and applied for/obtained an encroachment permit from the County.

1.2.3 Geologic Mapping – A compilation of readily available geologic mapping and data was prepared for the site area from regional geologic maps (Dibblee 1992; Weber, 1973). Geologic mapping was performed within the project limits on December 16, 2024, and during the subsurface exploration work in January 2025. Regional geology is presented on Figure 2 – Regional Geologic Map. Regional landslide maps are presented on Figures 3a and 3b – Landslide Inventory Map. Individual geologic maps and engineering geologic cross-sections depicting the distribution of earth materials and structural data within each of the four (4) mile post (MP) locations are presented on Figures 4a/4b through 7a/7b – Geologic Map and Geologic Cross-Section, respectively.

1.2.4 Subsurface Exploration – CSA conducted a subsurface exploration program, consisting of a combination of small-diameter (8") hollow-stem auger boring and hand-dug (24" by 36") test pits, in January 2025. We completed the following at each of the four (4) mile post (MP) locations:

- MP 0.93 two borings (B-9 and B-10) and two test pits (TP 04 and TP 05)
- MP 1.94 two borings (B-1 and B-2) and one test pit (TP 03)
- MP 2.61 three borings (B-6, B-7 and B-8) and two test pits (TP 01 and TP 02)
- MP 2.96 three borings (B-3, B-4 and B-5)

The borings at MP 1.94 were drilled on January 6, 2025, utilizing a truck-mounted GT8 drilling rig provided by 2R Drilling, Inc. of Chino, California. The borings at MP 0.93, 2.61 and 2.91 were drilled on January 13 and 14, 2025, utilizing a track-mounted CME 55 drilling rig provided by 2R Drilling, Inc. The borings ranged in depth from about 9 to 47 feet below ground surface (bgs). The exploratory test pits were excavated on January 20 and 21, 2025, utilizing hand labor provided by Mike's Excavating Service of Temecula, California. The test pits ranged in depth from about 5 to 6¹/₂ feet below ground surface (bgs). Summaries of field exploration procedures and boring and test pit logs are presented in Appendix A – Field Exploration.

1.2.5 Geotechnical Laboratory Testing – Laboratory tests were performed on selected disturbed and undisturbed soils samples obtained from the borings and test pits. Laboratory tests consisted of moisture content, wet and dry unit weight determinations, particle size analysis, #200 sieve wash analysis, Atterberg limits, direct shear strength, triaxial strength, maximum unit weight/optimum moisture content, expansion index, and general corrosion properties (resistivity, pH, sulfates and chlorides). The results of the laboratory testing program are presented in Appendix B – Laboratory Testing, and on our boring/test pit logs in Appendix A.

1.2.6 Geotechnical Evaluation and Reporting – Geotechnical evaluation at each of the four (4) sites consisted of characterizing field and laboratory test data and developing conclusions and recommendations regarding geotechnical and seismic hazards, excavatability and temporary excavation stability, and foundation type and design criteria. Based on data obtained from our subsurface exploration and geotechnical laboratory testing programs, we have formulated geotechnical opinions regarding site conditions and geotechnical hazards, and recommendations for the proposed improvements, including opinions regarding:

- Soil and groundwater conditions at each site;
- Site seismicity, and liquefaction and landslide potential;
- Seismic design parameters based on the 2022 California Building Code;
- Site preparation and grading and compaction requirements for fill placement below/behind structures and within other proposed development areas;
- Temporary excavations;
- Evaluation of onsite materials for use as compacted fill;
- Construction considerations including excavatability of the onsite materials;
- H-Pile and lagging;
- Preliminary pavement sections; and
- General corrosion potential of soil encountered in foundation and utility areas (limited soil chemistry testing: pH, resistivity, chloride and sulfate content)

2.0 SITE CONDITIONS

2.1 <u>Surface Conditions</u>

2.1.1 Regional Surface Conditions – The four (4) project site are located along Yerba Buena Road, a two-lane asphalt concrete roadway with an average width of twenty feet (20') located near the Pacific Ocean and the Ventura/Los Angeles County line in South Coast region of Ventura County. At its southern end, where it intersects Pacific Coast Highway, the first segment of Yerba Buena Road ascends 3.28 miles to its intersection with Cotharin Road. Yerba Buena Road is located in relatively

steep terrain along the southern flank of the western Santa Monica Mountains. The generally northsouth trending roadway, created through conventional cut/fill grading, is located along the eastern, relatively steep flank of the Little Sycamore Canyon drainage. Elevations within the project area ranges from approximately +300 feet at mile post (MP) 0.93 to approximately +1000 feet at mile post (MP) 2.96. The roadway and drainage primarily traverse marine sedimentary rocks, with relatively minor amounts of intrusive and interbedded volcanic rocks.

At MP 0.93, slopes descend from the western (southbound) margin of the roadway approximately ninety to one hundred feet (90'-100') toward Yerba Buena (i.e. Little Sycamore) Creek at gradients ranging from 1.5:1 (33°) to 1:1 (45°). A twenty-to-twenty-five-foot (20'-25') high, relatively steep (50°-55°) cut slope is present above the east (northbound) side of the road. Natural slopes continue to ascend approximately fifty-five to eighty feet (55'-80') to the crest of a southwest-trending ridgeline at gradients ranging to 1.5:1 (33°) to 1:1 (45°).

At MP 1.94, slopes descend from the north (southbound) margin of the roadway approximately sixty to sixty-five feet (60'-65') toward Yerba Buena (i.e. Little Sycamore) Creek at gradients ranging from 1.75:1 (30°) to, adjacent to the creek flowline, 1:1 (45°). Along the south (northbound) side of the roadway, slopes ascend approximately five hundred to five hundred twenty-five feet (500'-525') to a saddle and crest of a prominent east-west trending ridgeline at gradients ranging to 1.5:1 (33°) to 1:1 (45°).

At MP 2.61, slopes descend from the western (southbound) margin of the roadway approximately sixty to sixty-five feet (60'-65') toward Yerba Buena (i.e. Little Sycamore) Creek at gradients ranging from 1.75:1 (30°) to 1:1 (45°), and locally as steep as 53° along the Yerba Buena Creek flowline. An approximately twenty-foot (20') high, relatively steep ($50^\circ-55^\circ$) cut slope is present above the east (northbound) side of the road. Natural slopes continue to ascend approximately three hundred fifty feet (350') to the crest of a prominent south to southwest-trending ridgeline at gradients ranging to 1.5:1 (33°) to 1:1 (45°).

At MP 2.96, slopes descend from the western (southbound) margin of the roadway approximately sixty to seventy feet (60'-70') toward Yerba Buena (i.e. Little Sycamore) Creek at gradients ranging from $1.5:1 (33^{\circ})$ to $1:1 (45^{\circ})$. An approximately fifteen to twenty-foot (15'-20') high, relatively steep (50°-55°) cut slope is present above the east (northbound) side of the road. Natural slopes continue to ascend approximately three hundred twenty feet (320') to a grade break along the nose of an east-west trending spur ridge at gradients ranging to $1.5:1 (33^{\circ})$ to $1:1 (45^{\circ})$.

Following our record request, the County provided CSA with several documents, including an as-built plan set, dated August 27, 2020, for pavement resurfacing along Yerba Buena Road – South. In addition to miscellaneous drainage (catch basin, v-ditch, downdrains, culverts, etc.) improvements, the as-built plans indicate that this stretch of roadway was provided with a 2" thick asphalt concrete overlay.

2.1.2 Site-Specific Roadway and Slope Distress

The following was observed and noted at MP 0.93:

- Discontinuous, sub-linear to arcuate cracking along the graded dirt shoulder and western portion of the southbound travel lane, with the majority of this distress occurring between borings B-9 and B-10 (see Figure 4a). Roughly located in the center of the distressed area is a section of pavement, shoulder and embankment that has broken and vertically dropped approximately six to twelve inches (6"-12"), as measured along the top-of-slope.
- Evidence of relatively recent, relatively thin and localized slope failures was observed in the ascending slopes along the east side of the roadway. This includes instability in colluvium at the northern end of the County-provided mapping, where field mapping and logging of boring B-9 (Figure 4a) indicate the presence of an inactive, deeper landslide feature.
- Also observed just north of topographic mapping is pronounced, discontinuous and relatively linear cracks along the top of the descending roadway embankment. These cracks have occurred in what appears to be recent spill fill along the top of the roadway embankment.

The following was observed and noted at MP 1.94:

- Closely spaced, discontinuous, sub-linear to arcuate cracking along the graded dirt shoulder and western portion of the southbound travel lane between borings B-1 and B-2 (see Figure 5a). Some of the cracks have been previously patched and continue to open up, with evidence of both vertical/lateral offset and possible roadway settlement observed.
- Evidence of relatively recent, relatively thin and localized slope failures was observed in the ascending slopes along the east side of the roadway.

• Just north of a power pole and survey control point 3007 (see Figure 5a), outside the topographic survey limits, we observed an approximately fifty foot (50') long linear crack, with vertical and lateral offset, along the top-of-slope embankment.

The following was observed and noted at MP 2.61:

- Discontinuous, sub-linear to arcuate cracking along the top-of-slope and western portion of the southbound travel lane from south of survey control point 3009, and just outside the topographic survey mapping, north to boring B-6 (see Figure 6a). Some of the cracks have been previously patched and continue to open, with evidence of vertical/lateral offset and possible roadway settlement observed.
- Evidence of relatively recent, relatively thin and localized slope failures was observed in the ascending slopes along the east side of the roadway.
- Twelve feet (12') of earth fill was encountered in boring B-7. Along with our field mapping of the embankment slope below, this suggests a past slope failure and repair. None of the miscellaneous as-built documents provided indicate a previous repair in this area.

The following was observed and noted at MP 2.96:

- At the southern end of the survey mapping limits, the roadway embankment, edge of pavement and metal beam guard is locally undermined as a result of recent slumping within the surficial materials (fill and soil/colluvium), between borings B-3 and B-5 (see Figure 7a). Across the road, slumping and/or surficial failure(s) has occurred in colluvial materials on the ascending slope. Review of Google Earth[®] imagery indicates that these failures occurred during the 2023 winter rains.
- Occasional discontinuous, sub-linear to arcuate cracking along the top-of-slope and western portion of the southbound travel lane within the topographic survey mapping limits.
- Evidence of relatively recent, relatively thin and localized slope failures was observed in the ascending slopes along the east side of the roadway.

2.2 <u>Geologic Setting</u>

2.2.1 Regional Geology – The subject site is located within the western Santa Monica Mountains which are part of the Transverse Ranges geomorphic province. The Santa Monica Mountains are the southwestward most of the east-trending Transverse Ranges of southern California, extending from the Oxnard Plain approximately 80 kilometers west to the Los Angeles River. The Hollywood-Santa Monica and Malibu Coast fault zones form the southern boundary of the Transverse Ranges in this area. The Transverse Ranges geomorphic province consists of generally tightly folded Mesozoic and Cenozoic marine and non-marine sedimentary strata, extending from the Santa Ynez and San Gabriel Mountains on the north, the San Andreas Fault on the east, the Santa Monica Mountains (including the Santa Barbara Channel) on the south, to offshore west of Point Arguello (including the Santa Barbara Channel). The active tectonic stress environment acting upon this region since the late Tertiary consists of regional north-south oriented oblique transpression that has produced the characteristic east-west structural grain, and the series of east-west trending ranges and valleys within the province.

The western Santa Monica Mountains, including all four (4) project locations along Yerba Buena Road "South", are underlain by a thick accumulation of lower and middle Miocene marine sedimentary and volcanic rocks (Dibblee, 1988, 1990). Specifically, the project limits are underlain by early to middle Miocene sedimentary bedrock of the Lower Topanga Formation and occasional interbeds of volcanic rocks of the middle Miocene Conejo Volcanics. In many places the Topanga is injected by diabase sills and dikes of middle Miocene age (Dibblee, 1988). Yerkes and Campbell (1979) mapped the sediments underlying the project limits as the Encinal Member of the Topanga Formation, which they describe as chiefly relatively weak, dark gray siltstone or silty mudstone which is commonly platy to shaly with a dominant conchoidal fracture. Natural outcrops of the finegrained Topanga sediments are rare. These formations have been uplifted and deformed (gently folded) as a result of crustal compression and movement on regional fault systems, including the Hollywood-Santa Monica-Malibu Coast fault zones on the south.

The Lower Topanga Formation (aka Encinal Member of the Topanga Formation per Yerkes and Campbell, 1979) encountered in the project limits consists of interbedded brown to gray brown to gray siltstone, laminated siltstone and shale, with occasional beds of buff to brownish yellow to light gray fine-grained sandstone. The shale and siltstone beds are generally laminated to thinly bedded, slightly hard grading to hard, and highly to pervasively fractured. All of these bedrock units of the Lower Topanga Formation are considered rippable with heavy earth moving equipment but, as a combination of the bedding, hardness and fracturing, caving is likely in large-diameter borings or drilled shafts. Where observed/mapped in the roadway cuts and along the Yerba Buena creek channel at MP 2.94, the Conejo Volcanics Formation consists of brown to olive brown (weathered) to dark gray to black basalt which is fine-grained, slightly to moderately hard and massive to vaguely bedded.

Several significant-sized landslides within the Lower Topanga Formation are identified or queried on regional geologic maps within and near the limits of the four (4) project areas (Dibblee, 1990, California Division of Mines and Geology, 2002), and relatively smaller, previously unmapped or unrecognized landslides were identified by CSA through a combination of field mapping, subsurface exploration and aerial photo/topographic map interpretation. As shown on the enclosed Landslide Inventory Map (Figure 3a), the project at MP 0.93 is located just south of two (2) historically active landslides, as mapped by the State, and our subsurface investigation and field mapping indicates that landslide-affected materials extend onto the northern portion of the mapping/repair limits.

The project located at MP 1.94 is shown within the suspected (questionable, 50% confidence) limits of large inactive landslide complex and on the northern margin of a smaller, inactive landslide mapped with 75% confidence (Figure 3a). Our field mapping and subsurface exploration has confirmed the presence of landslide-affected materials at MP 1.94, and both to the north and south of MP 1.94. Further, landslide deposits were encountered in the subsurface and mapped at the northern end of the MP 2.61 project limits, and a slump affecting the roadway embankment was mapped at MP 2.96 (see Figures 7a and 7b). Landslide-affected materials within the four (4) project limits are depicted on Figures 4a through 7a.

2.2.2 Geologic Structure – With regard to the regionally mapped geologic structure, the four (4) project areas are located on the northern and southern limb of a significant regional anticlinal fold which trends through Yerba Buena Road at approximately MP 1.5 (Sequit Anticline of Dibblee, 1990); thus, regional geologic maps depict gentle to moderately steep north- and south-dipping bedding structure within the Lower Topanga Formation. Bedding within the Topanga Formation sediments mapped at MP 0.94 dips gently southward, while bedding at the MP 2.61 and 2.94 project locations dips gently northward. Hence, our site-specific mapping is generally consistent with the regional (Dibblee, 1990) trends. Small faults with minor dip-slip displacements (both normal and reverse slip) were observed within the bedrock mapped along cut slopes.

2.3 <u>Subsurface Conditions</u>

Subsurface conditions encountered during the field exploration program across the four (4) project sites generally consisted of artificial fill, natural soil and/or colluvium, and/or landslide deposits underlain by Lower Topanga Formation bedrock. On average, one to four and a half feet

(1-4¹/₂') of artificial fill, primarily associated with past cut/fill grading to construct the roadway, was encountered in each of the borings and test pits, with twelve feet (12') of artificial fill encountered in boring B-7. As previously mentioned, relatively thick landslide deposits were encountered in borings at three (3) of the project locations: boring B-9 at mile post (MP) 0.93, borings B-1 and B-2 at MP 1.94, and boring B-6 at MP 2.61.

2.3.1 Artificial Fill (Af) – Artificial fill (Af) generally consisted of a matrix of fine-grained silty sand to sandy silt to sandy clay and clayey, sandy silt/clayey silt with scattered to abundant rock fragments which is slightly moist to moist to slightly to moderately compact.

2.3.2 Natural Soil (Qs) / Colluvium (Qc) – Surficial natural soil (Qs) and/or colluvium (Qc) consists of clayey sand and sandy silt with scattered small rock fragments which is medium brown, slightly moist to moist, and loose or medium stiff with scattered roots and rootlets.

2.3.3 Landslide Deposits (Qls) – Where encountered in the borings, landslide deposits within the four (4) project areas generally consist of a of silty sand to sandy silt (matrix) with scattered to abundant siltstone and sandstone fragments which is light to medium brown, dry to moist, medium dense/dense to medium stiff/stiff. In general, these deposits are massive and relatively heterogeneous, vary from matrix- to clast-supported and locally grade with depth to sheared, highly to pervasively fractured, occasionally slickensided and highly weathered siltstone and clayey siltstone. Augering into these materials was challenging, particularly at MP 1.94. Difficult and slow augering, with the potential for sloughing and/or caving, should be anticipated at times during the drilling of cast-in-drilled-hole (CIDH) pile foundation excavations.

2.3.4 Lower Topanga Formation (Ttlc) – Bedrock of the Lower Topanga Formation (Ttlc) was encountered in most explorations. Formation materials consisted of predominantly thin- to mediumbedded layers of moderately weathered, closely fractured siltstone, clayey siltstone, shale and finegrained sandstone. Occasional thin beds of hard to very hard semi-siliceous siltstone were interspersed within the section explored. In general, weathering gradually decreased with depth while hardness inversely increased.

2.4 Groundwater Conditions

Across the four (4) project sites, no static groundwater was encountered to the maximum depth explored of 47 feet bgs. A review of historical high groundwater reported in the CDMG Seismic Hazards Zone Report for the Triunfo Pass quadrangle (CDMG, 2002) does not indicate the presence of a "Historically Shallow Groundwater Level" in the vicinity of the project sites. Given that the project sites are located approximately sixty feet (60') above the Yerba Buena Creek channel and

VCPWA – Yerba Buena Road Distress Page 10

underlain at relatively shallow depths by bedrock, with the exception of MP 1.94, it is unlikely that high static groundwater will negatively impact the project.

3.0 SEISMICITY

Seismicity evaluation for the project consisted of the assessment of earthquake hazards such as seismic setting and nearby faults, CBC seismic design criteria and estimated strong ground motion, as summarized below.

3.1 <u>Seismic Setting and Nearby Fault Sources</u>

The western Santa Monica Mountains is located in a very seismically active area. Historically, this area has been subjected to strong seismic ground shaking from major earthquakes and will continue to experience strong ground shaking in the future. The Malibu Coast fault zone is the closest controlling fault to MP 0.93 (about 1.60 kilometers from the project site). None of the four sites are located within an Alquist-Priolo Earthquake Fault Zone (APEFZ).

3.2 2022 CBC/ASCE/SEI 7-16 Seismic Design Criteria

Based on our geotechnical investigation, the site locations, our interpretation of the 2022 CBC and ASCE 7 Hazards Report for ASCE 7-16 related to Earthquake Loads and using the online tool, Table 1 below provides the parameter recommendations from the corresponding figures and tables. The ASCE 7 Hazards Report for each site is presented in Appendix C – Seismic Design Parameters.

Site	Parameter	Value
	Site Classification	С
	Mapped Spectral Acc. 0.2 Sec. (g)	Ss= 1.491
	Mapped Spectral Acc. 1 Sec. (g)	$S_1 = 0.521$
MD 0 92	$S_{MS} = F_a * S_s$	1.789
WII 0.93	$S_{M1} = F_v * S_1$	0.771
	$S_{DS} = 2/3*S_{MS}$	1.193
	$S_{D1} = 2/3^* S_{M1}$	0.514
	РСАм	0.722
	Site Classification	С
	Mapped Spectral Acc. 0.2 Sec. (g)	Ss= 1.484
	Mapped Spectral Acc. 1 Sec. (g)	$S_1 = 0.521$
MP 1 94	$S_{MS} = F_a * S_s$	1.781
1011 1.94	$S_{M1} = F_v * S_1$	0.769
	$S_{DS} = 2/3*S_{MS}$	1.187
	$S_{D1} = 2/3^* S_{M1}$	0.513
	РСАм	0.767
	Site Classification	С
	Mapped Spectral Acc. 0.2 Sec. (g)	Ss= 1.476
	Mapped Spectral Acc. 1 Sec. (g)	$S_1 = 0.518$
MP 2 61	$S_{MS} = F_a * S_s$	1.771
1011 2.01	$S_{M1} = F_v * S_1$	0.767
	$S_{\rm DS} = 2/3^* S_{\rm MS}$	1.181
	$S_{D1} = 2/3^* S_{M1}$	0.512
	РСАм	0.761
	Site Classification	С
	Mapped Spectral Acc. 0.2 Sec. (g)	Ss= 1.471
	Mapped Spectral Acc. 1 Sec. (g)	$S_1 = 0.516$
MP 2 96	$S_{MS} = F_a * S_s$	1.765
1911 2.90	$S_{M1} = F_v * S_1$	0.766
	$S_{DS} = 2/3*S_{MS}$	1.177
	$S_{D1} = 2/3^* S_{M1}$	0.511
	РСАм	0.758

Table 1. ASCE/SEI 7-16 Seismic Design Criteria

3.3 Peak Ground Accelerations

We performed a probabilistic seismic hazard analysis for each site using the USGS Unified Hazard Tool. Taking into account the regional faults described above, the 2022 California Building Code (CBC), the ASCE 7-16 code coefficient presented in Section 3.2, the results of the peak ground acceleration, and a return period of 475 years (i.e., 10% probability of being exceeded in 50 years), it is our opinion that the proposed improvements could experience peak horizontal ground accelerations as presented in Table 2 below. The computed uniform hazard response spectra each site are presented graphically in Appendix C.

Table 2. Peak Ground Acceleration Based on USGS Unified Hazard Tool

Site	PGA
MP 0.93	0.3714
MP 1.94	0.3751
MP 2.64	0.3745
MP 2.96	0.3778

4.0 SEISMIC GEOHAZARDS

In the following sections, we discuss potential seismic geohazards that may impact the subject site along with the corresponding degrees of estimated potential risk.

4.1 Faulting and Ground Rupture Potential

None of the four (4) project sites are located within a designated Alquist-Priolo Earthquake Hazard Zone (CGS, 1998). Active or potentially active faults are not known to exist on or trend toward the site. As such, the potential for primary ground surface rupture due to faulting is considered to be **low**.

4.2 <u>Tsunami and Seiche Hazard</u>

Based on the general site elevations (about 300 to 1000 feet) and distance to the Pacific Ocean, potential impacts from tsunami hazard are nil. In addition, there are not any nearby large bodies of landlocked surface water nearby and it is unlikely that any earthquake-induced seiche will impact the project site.

4.3 Liquefaction Potential and Related Settlement

Liquefaction occurs when saturated, loose to medium dense, sands and low-plasticity silts and clays are subjected to seismically-induced strong shaking. Liquefiable soils typically lose a portion or all of their shear strength and regain strength sometime after the shaking stops. Soil movements, both vertical and lateral, can occur as a result of liquefaction and ground shaking.

The project locations (4) are not located within a mapped Liquefaction Hazard Zone (aka, Zone of Required Investigation) by the State of California under the Seismic Hazards Mapping Act of 1990. In addition, groundwater is assumed to be much greater 50 feet deep and the bedrock is composed primarily of plastic fine-grained materials. As such, the potential for liquefaction is considered to be very low within the project limits.

4.4 Landslide and Slope Instability

The four (4) project sites are located within a Mapped Landslide Hazard Zone by the State of California (CGS 2002). Further, as previously discussed above, our investigation has identified that northern portions of the project/mapping limits at MP 0.93 and 2.61 are underlain by ancient landslide-affected materials and the entirety of the MP 1.94 project limits is within a relatively massive landslide complex, as mapped by the State of California (2002).

The Yerba Buena Road alignment is a relatively narrow, two-land roadway created via cut/fill grading along steep slopes above Yerba Buena Creek. In addition to the four (4) project sites, we observed many additional areas of distressed pavement and/or downslope embankment erosion/slippage/slope failure between the various project locations.

The potential exists for rock falls, surficial failures and similar slope instability to affect the existing cut slopes on the eastern and/or southern sides of Yerba Buena Road at all four (4) project sites. This potential is particularly acute at the following locations: (1) the northern map/project limits at MP 0.93, where colluvium and/or landslide-affected materials have been mapped and signs of very recent slope instability were observed; (2) the landslide-affected materials exposed and mapped all along the entire length of the MP 1.94 map/project limits ; (3) the northern map/project limits at MP 2.61, where landslide-affected materials have been mapped; (4) anywhere where slope instability has removed vegetation and surficial materials (soil, slopewash, colluvium, etc.) are exposed.

The potential exists for continuing erosion, surficial material (soil, slopewash colluvium, landslide debris) settlement and/or creep, surficial failures and similar slope instability to affect the relatively steep slopes below the future slope (roadway) stabilization at all four (4) project sites.

5.0 <u>CONCLUSIONS AND RECOMMENDATIONS</u>

The conclusions and recommendations for site grading and slope repair alternatives, as presented below, are based on our subsurface exploration, limited laboratory testing, and our experience with similar projects. Recommendations presented below should be incorporated into the project plans and specifications and should be adhered to during construction. Prior to contract bidding, construction plans should be reviewed by Cotton, Shires & Associates for consistency with our recommendations.

5.1 <u>Alternative Repair Options</u>

5.1.1 Do Nothing Option – The County has requested an evaluation of alternative repair options, including a do-nothing option. If the pavement and subgrade soils at the sites are not supported, then they will eventually fail and move downslope, and the roadway limits may be compromised or impinged for through traffic. Soil failure could occur at any time, but will most likely fail because of saturation from rainfall, traffic vibrations, or an earthquake. At a minimum, the County should continue sealing the cracks in the visibly distressed areas, which will help decrease infiltration into the subgrade soils. However, even with a proactive crack sealing program water will still be able to infiltrate the subgrade materials, and the distressed areas will continue to creep downslope/fail at some point in the future.

5.1.2 Soil Nail Walls – Another repair option would be to stabilize the adjacent slopes with soil-nail retaining wall systems. A soil-nail wall would consist of metal bars generally about one-inch in diameter grouted into four- to six-inch diameter (approximate) drill holes placed on a grid pattern on the slope below the roadway. The spacing of the grid-pattern is evaluated as part of a soil-nail slope support design based on the engineering parameters for the soil and rock materials, and other loading (traffic, seismic, etc.). Once the soil-nails are installed and grouted, a reinforced-concrete cover would be placed over the slope to help keep the loose, soft soil materials from moving downslope between the soil-nails.

Due to the relatively steep slopes, shallow soil conditions, and bedding at each site, soil-nail walls would be relatively challenging to construct and likely more expensive than the H-pile walls described below. In addition, the loose surficial fills at each site will continue to settle and cause cracking and distress to the pavement. Loose fill would need to be removed and replaced as compacted fill as part of the project improvements, even with the installation of soil nail walls.

5.1.3 H-Pile Wall – Several segments of Yerba Buena Road have already been repaired or improved with H-pile walls that appear to be performing well, including the 2020/21 repair completed by the County at MP 0.55, which was to mitigate distress conditions similar to those

observed at the four sites in this study. Based on the relatively shallow soil depth to be retained at each site, as well as the relatively shallow bedrock or landslide materials available for support, the H-pile repair option appears to be the preferred option at each site from a geotechnical perspective. Similar to the soil nail wall option discussed above, remedial grading and re-paving within the distressed areas will be required in order to remove the upper loose materials and improve drainage. This remedial grading should be conducted after the H-pile walls have been installed.

5.1.4 Repair of Upslope Areas – The County has requested a discussion of upslope areas observed during our distress evaluations that warrant what we consider immediate closer evaluation. As stated above, the potential exists for rock falls, surficial failures and similar slope instability to affect the existing cut slopes on the eastern and/or southern sides of Yerba Buena Road at all four (4) project sites.

Within the limits of our study, there are two (2) locations where, for the reasons listed below, we are recommending immediate closer evaluation. At location #1, the northern map/project limits at MP 0.93 (Figure 4a), tension cracks and signs of recent slope failure(s) were observed within colluvium and landslide-affected materials exposed in the relatively steep cut slope. Future failure(s) have the potential to impact the northbound travel lane. At location #2, the southern map/project limits at MP 2.96 (Figure 7a), recent (2023) slumping and/or surficial failure(s) have occurred in colluvial materials on the ascending slope.

Possible repair alternatives at these locations may include Tecco[®] mesh with soil nails, or slope lay-back to reduce over-steepened conditions, or impact walls between the slope and roadway, along with drainage improvements which may include concrete brow or v-ditches to direct overland surface flow away from the areas of potential failure. Any option regarding upslope repairs would need to consider limitations imposed by property (right-of-way) limits.

These areas require more in-depth mapping, exploration and evaluation than what was conducted for this pavement distress study. If the County requests further evaluation of repair alternatives, then we can prepare a separate scope for that work.

5.2 Site Development and Grading

5.2.1 Site Preparation – Prior to commencing grading operations, soil materials containing debris, organics, pavement, or other unsuitable materials should be stripped from the structure areas. Demolition of on-grade improvements should include removal of pavements, slabs, abandoned utilities, and soils disturbed during the demolition process. All existing artificial fill located within the footprint of the proposed improvements (as determined by a CSA representative in the field).

Depressions or disturbed areas left from the removal of such material should be replaced with compacted fill.

5.2.2 Excavation Considerations – The earth materials underlying the site should be generally excavatable with heavy-duty earthwork equipment in good working condition. We note the excavation for the planned repair alignment has the potential for difficult excavation conditions (caving and hard drilling zones) in the bedrock materials. Also, we recommend existing utilities be removed from the grading areas and relocated as necessary. A small amount of oversize materials consisting of very hard concretionary siltstone may be generated during site excavations. These materials may not reduce below boulder size through normal cutting and filling operations.

5.2.3 Temporary Excavations – Excavations up to a maximum of about 8 feet in height are anticipated for construction of the preferred slope repair alternative. Excavations are expected to expose artificial fill, natural soil/colluvium (locally), landslide deposits (locally) and moderately hard, fractured and weathered bedrock material consisting of siltstone, shale, semi-siliceous siltstone and fine-grained sandstone. Material should be suitable for vertical excavations up to 5 feet in height where not surcharged by adjacent traffic or structures. Non surcharged temporary excavations greater than 5 feet should be trimmed and laid back at a maximum gradient of 1/2:1 (horizontal to vertical), for the full height of the excavation.

Where sloped embankments are utilized, the tops of the slopes should be barricaded to prevent vehicles and storage loads within a horizontal distance equal to the depth of the excavation. If temporary construction embankments are to be maintained during the rainy season, berms are suggested along the top of slopes where necessary to prevent runoff water from entering the excavation and eroding slope faces. Water should not be allowed to pond on top of the excavation nor flow toward it.

Temporary slopes and excavations should conform to Federal Occupational Safety and Health Administration (OSHA) and/or California Division of Occupational Safety and Health (DOSH) regulations and other applicable local ordinances and building codes, as required. However, the contractor should be made responsible for all safety issues regarding open excavations.

5.2.4 Subgrade Preparation – The finished subgrade surface exposed after over-excavation should be scarified to a depth of 12 inches, moisture-conditioned or dried back to within 0 to 2 percent of optimum moisture and compacted to a relative compaction of at least 90 percent (i.e., 90 percent of the maximum dry density determined from ASTM D1557). Bedrock areas do not need to be over-excavated or scarified.

5.2.5 Fill Material Selection – Recommended fill material selection requirements for subgrade fill, aggregate base, and use of onsite materials are presented below. Areas or zones where the various fill materials may be used are described below.

5.2.5.1 Subgrade Fill – General fill should be free of organics, oversize rock (greater than 3 inches in diameter), trash, debris, and other deleterious or unsuitable materials, and should have an expansion index less than 50 and an R-value of 15 or greater.

5.2.5.2 Aggregate and Miscellaneous Base – Aggregate or miscellaneous base material should be placed below the asphalt pavement. Base materials should consist of imported material conforming to Caltrans Standard Specifications for Class 2 Aggregate Base, Section 26-1.02 (Caltrans, 2020) or Section 200-2.5 of the Greenbook (2018) for Processed Miscellaneous Base. The base materials should have a minimum R-value of 78.

5.2.5.3 Use of Onsite Materials – Materials generated during excavation and grading in pavement areas are generally anticipated to consist of a mixture of fine-grained soil materials with gravel-size and larger rock fragments. Material derived from the over-excavation can be used as subgrade as long as those materials satisfy criteria presented above for subgrade fill and if they are moisture conditioned to near the optimum moisture content (0 to + 2 percent of optimum content). Rocks larger than 4 inches in maximum dimension should be removed from onsite soils to be used as compacted fill. Cobble-size clasts exceeding this dimension were observed in the colluvial soils on the site, and some boulder-size clasts are likely to be generated in excavations within the site bedrock materials

5.2.5.4 Imported Fill – Imported subgrade fill materials should comply with recommendations for subgrade fill or as appropriate for its intended use. Imported fill should be reviewed by the geotechnical engineer prior to being transported to the site.

5.2.6 Fill Placement – Fill materials should be spread evenly, with loose lifts no thicker than eight inches, and should be thoroughly blade-mixed during spreading to provide relative uniformity of material within each layer. Soft or yielding materials should be removed and replaced with properly compacted fill material prior to placing the next layer.

5.2.7 Compaction Requirements – Fill material placed up to one-foot below the pavement section or retaining structures should be compacted to a relative compaction of at least 90 percent of the maximum dry density determined from ASTM D1557, latest edition. Subgrade fill materials placed within one-foot of the pavement section should be compacted to a relative compaction of at least 95 percent of the maximum dry density. As-compacted moisture contents for subgrade fill

materials should be within 0 to +2 percent of the optimum moisture as determined from ASTM D1557.

5.2.8 Import Fill – Import fill, if required for the project, should be well-graded granular materials with the following characteristics:

- Non-expansive (EI \leq 20).
- Friction angle \geq 30 degrees.
- Maximum particle size < 2 inches.
- Percentage passing the No. 4 sieve between 60 and 100.
- Percentage passing the No. 200 sieve between 10 and 30.
- Plasticity Index < 10.

5.2.9 Cut/Fill Slope Design – All new permanent cut slopes should not exceed an inclination of 2:1 (H:V). All permanent fill slopes constructed with onsite excavated earth materials should have a maximum inclination of 2:1 (H:V). Fill materials placed on slopes steeper than 6:1 should have a keyway excavated into competent bedrock or competent native materials at the toe no less than 10 feet wide, 2 feet deep into bedrock or competent native materials at the toe, 3 feet deep into bedrock or competent native materials at the toe, 3 feet deep into bedrock or competent native materials at the toe, 1 foot into competent bedrock or competent native materials as the fill slope is brought up to grade. The exposed subgrade should be inspected by our representative for firmness prior to placement of any new fill materials.

5.3 <u>H-Pile Wall Design</u>

Based on the results of the subsurface exploration program for this study, and other repairs undertaken by the County for similarly distressed areas along Yerba Bunea Road, we anticipate that H-piles with lagging will be the preferred distress repair option from a geotechnical perspective. The upper artificial fill materials are likely to settle and deform around new H-piles, and cause distress to the existing pavement if left in-place. The repair project should therefore include removal and compaction of the upper artificial fill materials the H-pile system has been installed, in accordance with the recommendations presented in Section 5.1 above. This section provides foundation design parameters for an H-pile wall similar to the wall installed at MP 0.55 in 2020.

5.3.1 Drilled Shaft Foundations – Drilled shaft foundations should have a minimum embedment of 10 feet into intact siltstone bedrock of the Topanga Formation, or at least 12 feet into Landslide Deposits if the depth to Topanga Formation is prohibitive. In addition, the drilled shaft/pile design will need to consider:

- Traffic loading (if the County applies traffic loading to wall design);
- Use of concrete beam lagging to reduce damage associated with fire;
- Compaction of upper artificial fill materials in the zone between the piles and mapped cracks after installation of the piles is complete; and
- Wall drainage or include saturated soil loading in design.

5.3.2 CIDH Piles – Axial capacity values for a steel H-pile placed in a 24-inch diameter drilled hole are summarized below for end bearing, compression, and tension. Pile design assumes a minimum cast-in-drilled hole (CIDH) pile drilled shaft diameter of 24-inches. Additional axial design recommendations are presented in Table 3 below.

			Allowable	
		Allowable	Shaft	
	Allowable	Shaft Friction	Friction	
Mile	End Bearing	(compression),	(tension),	Minimum Embedment
Post	(compression), psf	psf	psf	Depth (ft)
MD 0.02	4,000	600	300	10 feet into Topanga Formation
MIP 0.93	3,000	500	250	12 feet into Landslide Deposits
MP 1.94	3,000	500	250	12 feet into Landslide Deposits
MD 2 61	4,000	600	300	10 feet into Topanga Formation
WIF 2.01	3,000	500	250	12 feet into Landslide Deposits
MP 2.96	3,000	500	250	12 feet into Landslide Deposits

Table 3. Summary of CIDH Allowable Axial Design Values

Caissons may derive lateral bearing support (i.e., passive pressure) from that portion of the pile in contact with the allowable bearing material in accordance with the parameters presented in Table 4 below. The values in Table 4 assume descending ground to the north or west (downslope) of the piles, and level ground at the roadway.

 Table 4. Summary of CIDH Allowable Lateral Design Values

			Maximum
		Allowable	Allowable
	Allowable Bearing	Lateral Bearing	Lateral Bearing
Mile Post	Material	Pressure psf/ft	Pressure psf/ft
MD 0.02	Topanga Formation	450	3,500
MP 0.93	Landslide Deposits	300	2,500
MP 1.94	Landslide Deposits	300	2,500
MD 2 61	Topanga Formation	450	3,500
WIF 2.01	Landslide Deposits	300	2,500
MP 2.96	Landslide Deposits	300	2,500

COTTON, SHIRES AND ASSOCIATES, INC.

The depth of allowable bearing material shall be the elevation of firm, in-place bedrock or landslide deposits. This position shall be assumed to lie three vertical feet below the upper contact of this material. Below this depth of approved bearing material, the foundation may receive credit for lateral passive support, frictional resistance and bearing capacity. In addition, the lateral support may begin below a depth that ensures a 10-foot lateral daylight to the descending slope. The depth of the piles may need to be adjusted in the field based on the actual soil conditions encountered in the drill shaft excavations.

For lateral loading, caissons may be considered fully isolated at a spacing of at least three (3) shaft diameters. All caissons shall be designed to resist a down-slope creep-force of 1,000 pounds per foot of depth, for all soil, colluvium and/or uncertified fill materials encountered above the depth of allowable bearing material. Caissons shall be no closer together than two (2) shaft diameters (measured edge-to-edge) for ease of drilling.

If significant water is present within the caisson excavation (not anticipated), then concrete shall be placed in a manor approved by the project design engineer. Additionally, and as a minimum, when significant water is present within the excavation, the concrete mix shall be increased by at least 1,000 psi over the design psi; however, the designer shall specify the specific changes to the design psi and/or the inclusion of special additives into the design mix to mitigate potential dilution and/or segregation of the paste during placement.

5.3.3 CIDH Installation Considerations – As described above and depicted in Appendix A, the subsurface materials consist of surficial artificial fill underlain by colluvium and landslide deposits, and/or fractured siltstone and sandstone bedrock of the Topanga Formation. These materials have the potential to cave in open excavations. Drilling at MP 1.94 was noted to be occasionally very difficult due to encountering hard oversize materials (cobbles and boulders) in the landslide-affected materials. In addition, the landslide deposits and bedrock materials consist of weak to moderately hard, highly fractured, siltstone bedrock that could cave along fractures and near-vertical bedding planes. There is also the potential to encounter layers of hard, well cemented sandstone, chert, and other zones of hard drilling in the Topanga Formation bedrock.

5.3.4 Lagging – The earth materials anticipated within the depth of lagging are expected to vary significantly. It is recommended that the exposed earth materials be observed by a geotechnical professional to verify the cohesive nature of the earth materials. We understand that wood lagging is not preferred because it could burn in a fire. One mitigation could be to install concrete beam lagging to provide fire protection. It is recommended that the lagging be designed for the full design pressure, but may be limited to a maximum of 400 psf.

Given the erosion potential of the relatively steep, downhill embankment slopes across the four (4) project locations, it is recommended that the lagging extend into bedrock and/or competent native materials a minimum of twelve inches (12") and no less than three (3) feet below finish grade along the outer edge of the retaining wall profile. An exception to this is at MP 2.96 where, due to the proximity of a recently active slump and associated steep head scarp(s), we recommend that the lagging extend into bedrock and/or competent native materials a minimum of twelve inches (12") and no less than five (5) feet below finish grade along the outer edge of the retaining wall profile.

5.4 <u>Replacement of Existing Asphalt Concrete Pavement</u>

At a minimum, we recommend that existing asphalt concrete pavement sections be replaced with an equal thickness as asphalt concrete, plus 1 inch. Granular base materials should be replaced with an equal thickness of Caltrans Class II base, Crushed Aggregate Base, or Processed Miscellaneous Base in accordance with the Greenbook (2021). The existing pavement sections at the completed boring locations were recorded during our field exploration, and are shown on the respective borings logs.

5.5 <u>General Corrosivity Considerations</u>

A bulk sample of materials obtained from a boring at each site was tested for resistivity, pH sulfates, and chlorides at the proposed depth of the tank. The results are presented in Table 5 below.

Site	Boring/Sample Depth	Material Description	Resistivity (ohm)	pН	Sulfates (%)	Chlorides (%)
MP 0.93	B-10 @ 11 feet	Topanga Formation	2,700	6.4	0.008	0.001
MP 1.94	B-2 @ 6 feet	Landslide Deposits	3,100	6.3	0.009	0.001
MP 2.61	B-8 @ 6 feet	Topanga Formation	3,300	6.1	0.006	0.001
MP 2.96	B-5 @ 3.5 feet	Topanga Formation	6,200	6.3	0.008	0.001

Table 5. Summary of Corrosivity Test Results

The resistivity values presented above suggest that materials in the project area are moderately corrosive to underground steel (Caltrans, 2020). Tests results for sulfates indicate that onsite soils may be classified as S1 per ACI 318 Table 19.3.1.1. On the basis of sulfate concentration, we recommend that Type II cement be used for concrete in contact with earth materials, in accordance with CBC Chapter 19A (2022).

CSA does not practice in the field of corrosion engineering and the test results presented herein are preliminary. Test results should be evaluated by a qualified corrosion engineer to assess how structures and underground utilities should be protected from anticipated subsurface materials.

5.6 <u>Technical Review</u>

This report, and any supplemental recommendations, should be reviewed by the contractor as part of the bid process. Supplemental geotechnical design recommendations should be provided by our firm based on specific design needs developed by the other project design professionals. It is strongly recommended that no construction be commenced nor grading undertaken until the final drawings, specifications, and calculations have been reviewed and approved in writing by a representative of our firm.

5.7 Earthwork Construction Inspection Testing

All excavations should be inspected by a representative of our firm during site grading and pile installation. Grading should also be inspected and tested, as appropriate, to confirm adequate stripping, subgrade preparation, and compaction of engineered fill. Our office should be contacted within a minimum of 48 hours' advance notice of construction activities requiring inspection and/or testing services.

6.0 INVESTIGATION LIMITATIONS

Our services consist of professional opinions and recommendations made in accordance with generally accepted engineering geology and geotechnical engineering principles and practices. No warranty, express or implied, or merchantability or fitness, is made or intended in connection with our work, by the proposal for consulting or other services, or by the furnishing of oral or written reports or findings.

This report has been prepared for the exclusive use of the Ventura County Public Works Agency and their authorized agents for design considerations for the Yerba Buena Road Distress project in Ventura County, California. This report is issued with the understanding that it is the responsibility of the owner, or of his representative, to ensure that the information and recommendations contained herein are called to the attention of the project architect and/or engineer and incorporated into the design plans, as appropriate.

7.0 <u>REFERENCES</u>

Documents Reviewed

California Building Code (CBC) (2022), International Conference of Building Officials, July 1.

California Department of Transportation (Caltrans, 2020), Corrosion Guidelines, Version 2.1, January.

California Department of Water Resources (2018), Water Data Library: http://www.water.ca.gov/waterdatalibrary/.

California Department of Conservation, Division of Mines and Geology, 2002, Seismic Hazard Zone Report for the Triunfo Pass 7.5-Minute Quadrangle, Los Angeles and Ventura Counties, California, Seismic Hazard Zone Report 059.

Highway Design Manual (2020). Chapter 620 Rigid Pavement. November 20.

- Public Works Standards, Inc. (PWS) (2021), "Greenbook," Standard Specifications for Public Works Construction, published by BNI Building News.
- T.W. Dibblee, Jr., 1988, Geologic Map of the Western Santa Monica Mountains, in *Ventura Basin: Geologic Introduction and Field Trip Guidebook*, published by the Pacific Section of AAPG.
- T.W. Dibblee, Jr., 1990, Geologic Map of the Point Mugu & Triunfo Pass Quadrangles, Ventura and Los Angeles Counties, California, Scale 1:24,000. Dibblee Foundation Map No. DF-29, dated November 1990.
- U.S. Geological Society, 2020, 2008 National Seismic Hazard Maps Source Parameters, Earthquake Hazards Program, <u>https://earthquake.usgs.gov/cfusion/hazfaults_2008_search/query_main.cfm</u>.

____, 2018a, TopoBuilder Application version 1.3.3: <u>https://topobuilder.nationalmap.gov/.</u>

_____ 2018b, Unified Hazard Tool website: https://earthquake.usgs.gov/hazards/interactive/.

_____ 2018c, U.S. Quaternary Fault database website:

https://usgs.maps.arcgis.com/apps/webappviewer/index.html?id=5a6038b3a1684561a9b0aadf88412f cf

Yerkes, R.F. and Campbell, R.H., 1979, Stratigraphic Nomenclature of the Central Santa Monica Mountains, Los Angeles County, California, United States Geological Survey Bulletin 1457-E. VCPWA – Yerba Buena Road Distress Page 24

Yerkes, R.F. and Campbell, R.H. (compilers), 2005, Preliminary Geologic Map of the Los Angeles 30' x 60' Quadrangle, Southern California, Version 1.0, U.S. Geological Survey Open-File Report 2005-1019, scale 1:100,000.

Aerial Photographs Reviewed

- University of California Santa Barbara, Map and Imagery Library, December 1935. *Flight C-3814* [air photo]. Scale 1:18,000. Frames 43, 44, 45 and 46, UCSB FrameFinder URL: <u>http://mil.library.ucsb.edu/ap_indexes/FrameFinder/</u>, accessed October 2024 and February 2025.
- ____, October 1945. *Flight C-9800* [air photo]. Scale 1:14,400. Frames 15-1549, 6-527, 6-528, and 7-569, UCSB FrameFinder URL: <u>http://mil.library.ucsb.edu/ap_indexes/FrameFinder/</u>, accessed October 2024 and February 2025.

FIGURES



Reference: Modified from the Topographic Map of the Triunfo Pass Quadrangle, prepared by U.S.G.S., 1994.

COTTON, SHIRES AND ASSOCIATES, INC. CONSULTING ENGINEERS AND GEOLOGISTS					
SITE VICINITY MAP YERBA BUENA ROAD DISTRESS MILE POSTS (MP) 0.93, 1.94, 2.61 & 2.96 Ventura County, CALIFORNIA					
GEO/ENG BY EPB/MJJSCALE 1" = 2000'PROJECT NO. SC6164					
APPROVED BY MJJ	DATE APRIL 2025	FIGURE NO. 1			



Tcvb/Tcvab Conejo Volcanics

db/api

Ttlc/Ttls

Diabase & Andesite (Intrusives)

Topanga Formation

COTTON, SHIRES AND ASSOCIATES, INC. CONSULTING ENGINEERS AND GEOLOGISTS						
REGIONAL GEOLOGIC MAP YERBA BUENA ROAD DISTRESS MILE POSTS (MP) 0.93, 1.94, 2.61 & 2.96						
	Ventura County, CALIFORNIA	4				
GEO/ENG BY EPB/MJJSCALE AS SHOWNPROJECT NO.SC6164						
APPROVED BY MJJ	DATE APRIL 2025	FIGURE NO. 2				



Reference: California Division of Mines and Geology, 2002, Plate 2.1, Seismic Hazard Zone Report for the Triunfo Pass 7.5-Minute Quadrangle, Los Angeles and Ventura Counties, California, Seismic Hazard Zone Report 059.

Ventura County, CALIFORNIAGEO/ENG BY
EPB/MJJSCALE
AS SHOWNPROJECT NO.
SC6164APPROVED BY
MJJDATE
APRIL 2025FIGURE NO.
3a



Quadrangle, Los Angeles and Ventura Counties, California, Seismic Hazard Zone Report 059.

EPB/MJJ	AS SHOWN	SC6164
APPROVED BY MJJ	DATE APRIL 2025	FIGURE NO. 3b



LEGEND

af	= artificial fill
Qc	= Colluvium
Qal	= Alluvium
Qsf	= Surficial failure (recent)
Qs	= Slump (recent)
Qls	= Landslide debris and/or landslide-affected bedrock (inactive)
Tcvb	= Conejo Volcanics (middle Miocene geologic age)
Ttlc	= Lower Topanga Formation (early to middle Miocene geologic age)
•	= Hollow-stem auger boring
	= Hand-dug test pit
22	= Strike and dip of jointing
22	= Strike and dip of shear
22	= Strike and dip of bedding
	= Approximate geologic contact
	= Geologic cross-section
	= Pavement cracks 0 10 20 40
	= Approximate limits of recommended remedial repair (feet)
	= Upslope area of Concern (see Report)

NOTE: This document has been created from a digital topographic base map prepared by Ventura County, provided January 27, 2025. Analyses and/or professional opinions generated from this plan a provided to this office. If discrepancies are found to exist between the plan(s) and the actual site conditions, they should be brought to our immediate attention so that revisions may be made as required



COTTON, SHIRES AND ASSOCIATES, INC. CONSULTING ENGINEERS AND GEOLOGISTS

GEOLOGIC MAP Yerba Buena Road Distress - Mile Post (MP) 0.93 VENTURA COUNTY, CALIFORNIA

	GEO/ENG BY	SCALE	PROJECT NO.
	EPB	1"=20'	SC6164
are only as accurate as the plan(s) ed.	APPROVED BY	DATE	FIGURE NO.
	EPB/MJJ	April 2025	4a



GEOLOGIC CROSS-SECTIONS Yerba Buena Road Distress - Mile Post (MP) 0.93 VENTURA COUNTY, CALIFORNIA PROJECT NO. GEO/ENG BY SCALE EPB 1"=20' SC6164 APPROVED BY DATE FIGURE NO. NOTE: This document has been created from a digital topographic base map prepared by Ventura County, provided January 27, 2025. Analyses and/or professional opinions generated from this plan are only as accurate as the plan(s) provided to this office. If discrepancies are found to exist between the plan(s) and the actual site conditions, they should be brought to our immediate attention so that revisions may be made as required. April 2025 4b EPB/MJJ






NOTE: This document has been created from a digital topographic base map prepared by Ventura County, provided January 27, 2025. Analyses and/or professional opinions generated from this plan are provided to this office. If discrepancies are found to exist between the plan(s) and the actual site conditions, they should be brought to our immediate attention so that revisions may be made as required.

<u>LEGEND</u>

af	= artificial fill
Qc	= Colluvium
Qal	= Alluvium
Qsf	= Surficial failure (recent)
Qs	= Slump (recent)
Qls	= Landslide debris and/or landslide-affected bedrock (inactive)
Tcvb	= Conejo Volcanics (middle Miocene geologic age)
Ttlc	= Lower Topanga Formation (early to middle Miocene geologic age)
\bullet	= Hollow-stem auger boring
	= Hand-dug test pit
22	= Strike and dip of jointing
<u>22</u> ↑	= Strike and dip of shear
22	= Strike and dip of bedding
	= Approximate geologic contact
	= Geologic cross-section
	= Pavement cracks
\square	 Approximate limits of recommended remedial repair

COTTON, SHIRES AND ASSOCIATES, INC. CONSULTING ENGINEERS AND GEOLOGISTS

GEOLOGIC MAP Yerba Buena Road Distress - Mile Post (MP) 1.94 VENTURA COUNTY, CALIFORNIA

	,								
	GEO/ENG BY	SCALE	PROJECT NO.						
	EPB	1"=20'	SC6164						
re only as accurate as the plan(s)	APPROVED BY EPB/MJJ	DATE April 2025	FIGURE NO. 5a						

ELEVATION IN FEET (ABOVE SEA-LEVEL)

NOTE: This document has been created from a digital topographic base map prepared by Ventura County, provided January 27, 2025. Analyses and/or professional opinions generated from this plan provided to this office. If discrepancies are found to exist between the plan(s) and the actual site conditions, they should be brought to our immediate attention so that revisions may be made as requir

GEOLOGIC CROSS-SECTIONS Yerba Buena Road Distress - Mile Post (MP) 1.94

VENTURA COUNTY, CALIFORNIA

	GEO/ENG BY	SCALE	PROJECT NO.
	EPB	1"=20'	SC6164
n are only as accurate as the plan(s)	APPROVED BY	DATE	FIGURE NO.
red.	EPB/MJJ	April 2025	5b

NOTE: This document has been created from a digital topographic base map prepared by Ventura County, provided January 27, 2025. Analyses and/or professional opinions generated from this plan a provided to this office. If discrepancies are found to exist between the plan(s) and the actual site conditions, they should be brought to our immediate attention so that revisions may be made as required

GEOLOGIC MAP Yerba Buena Road Distress - Mile Post (MP) 2.61 VENTURA COUNTY, CALIFORNIA

	GEO/ENG BY	SCALE	PROJECT NO.
	EPB	1"=20'	SC6164
are only as accurate as the plan(s)	APPROVED BY	DATE	FIGURE NO.
ed.	EPB/MJJ	April 2025	6a

ELEVATION IN FEET (ABOVE SEA-LEVEL)

NOTE: This document has been created from a digital topographic base map prepared by Ventura County, provided January 27, 2025. Analyses and/or professional opinions generated from this plan as provided to this office. If discrepancies are found to exist between the plan(s) and the actual site conditions, they should be brought to our immediate attention so that revisions may be made as required.

	CONSULTIN	NG ENGINEERS AND GEO	DLOGISTS								
	GEOI Yerba Buena	GEOLOGIC CROSS-SECTIONS Yerba Buena Road Distress - Mile Post (MP) 2.61									
	WEST MALIBU, VENTURA COUNTY, CALIFORNIA										
	GEO/ENG BY EPB	SCALE 1"=20'	PROJECT NO. SC6164								
re only as accurate as the plan(s)	APPROVED BY EPB/MJJ	DATE April 2025	FIGURE NO. 6b								

<u>LEGEND</u>

af	= artificial fill
Qc	= Colluvium
Qal	= Alluvium
Qsf	= Surficial failure (recent)
Qs	= Slump (recent)
Qls	= Landslide debris and/or landslide-affected bedrock (inactive)
Tcvb	= Conejo Volcanics (middle Miocene geologic age)
Ttlc	= Lower Topanga Formation (early to middle Miocene geologic age)
\bullet	= Hollow-stem auger boring
	= Hand-dug test pit
22	= Strike and dip of jointing
22	= Strike and dip of shear
22	= Strike and dip of bedding
	= Approximate geologic contact
	= Geologic cross-section
	= Pavement cracks
	= Approximate limits of recommended remedial repair
2	= Upslope area of Concern (see Report)

NOTE: This document has been created from a digital topographic base map prepared by Ventura County, provided January 27, 2025. Analyses and/or professional opinions generated from this plan a provided to this office. If discrepancies are found to exist between the plan(s) and the actual site conditions, they should be brought to our immediate attention so that revisions may be made as required

COTTON, SHIRES AND ASSOCIATES, INC. CONSULTING ENGINEERS AND GEOLOGISTS

GEOLOGIC MAP Yerba Buena Road Distress - Mile Post (MP) 2.96 VENTURA COUNTY, CALIFORNIA

	GEO/ENG BY	SCALE	PROJECT NO.
	EPB	1"=30'	SC6164
are only as accurate as the plan(s) ed.	APPROVED BY EPB/MJJ	DATE April 2025	FIGURE NO. 7a

SCALE (H & V): 1" = 20'

NOTE: This document has been created from a digital topographic base map prepared by Ventura County, provided January 27, 2025. Analyses and/or professional opinions generated from this plan a provided to this office. If discrepancies are found to exist between the plan(s) and the actual site conditions, they should be brought to our immediate attention so that revisions may be made as required

VENTURA COUNTY, CALIFORNIA

	GEO/ENG BY	SCALE	PROJECT NO.
	EPB	1"=20'	SC6164
are only as accurate as the plan(s)	APPROVED BY	DATE	FIGURE NO.
ed.	EPB/MJJ	April 2025	7b

APPENDIX A FIELD EXPLORATION

APPENDIX A – FIELD EXPLORATION

EXPLORATORY BORINGS

CSA completed multiple subsurface exploration programs between January 6 and 14, 2025, where ten (10) total exploratory borings were conducted within the four (4) project sites. The completed borings ranged in depth from about 9 to 47 feet below ground surface (bgs) and were excavated by means of either truck- or track-mounted drill rigs equipped with 8-inch diameter hollow-stem augers provided by 2R Drilling of Chino, California. The locations of the ten (10) completed borings are shown on Figures 4a to 7a.

Borings were logged by a CSA registered geologist. Subsurface materials were visually classified in accordance with ASTM D-2487 or ASTM D-5434, as applicable. Bulk samples, relatively undisturbed, and disturbed samples were obtained of the materials encountered at selected depths. Relatively undisturbed samples were obtained with a 3-inch diameter modified split-barrel California Sampler and disturbed samples were obtained with a 2-inch diameter split barrel standard penetration sampler. Both samplers were driven by an automatic, 140-lb hammer dropped from a height of 30 inches. The relatively undisturbed samples were typically collected in brass liners that were 2.5 inches in outside diameter and 1 inch tall.

Logs of the borings are presented as Figure Nos. A-1 through A-10. A summary of terms and symbols used in the logs is shown in Figure No. A-0. The logs depict our interpretation of the subsurface conditions at the date and location indicated based on representative samples collected during drilling. It is not warranted that they are representative of subsurface conditions at other times and locations. The contacts on the log represent the approximate boundaries between earth materials, and the transitions between these materials may be gradual.

TEST PITS

Test pits were excavated at five (5) locations across the four (4) project sites. The test pits were excavated between January 20 and 21, 2025, by means of hand equipment provided by Mike's Excavating of Temecula, California. The test pits ranged in depth from about 5 to 6.5 feet bgs. Relatively undisturbed samples were obtained within the test pits through the use of a thin-walled, steel, hand-held sampler. The test pit locations are shown on Figures 4a to 7a.

VCPWA – Yerba Buena Road Distress Page A-2

Logs of the test pits are presented as Figure Nos. A-11 through A-13. The logs depict our interpretation of the subsurface conditions at the date and location indicated based on exposures and representative samples collected during excavation. It is not warranted that they are representative of subsurface conditions at other times and locations. The contacts on the logs represent the approximate boundaries between earth materials, and the transitions between these materials may be gradual.

COTTON, SHIRES AND ASSOCIATES, INC. LOG OF EXPLORATORY DRILLING												
Projec	ct:	١	/CPW	/A - Ye	erba Buena Road Distress Logged By:	EP	<u>B</u> P	roject l	Numbe	er: <u>SC</u>	6164	Boring: B-1
Locat	ion:				MP 1.94	Eleva	ation (ft):62	<u>25</u>	Weathe	er:	Clear/warm
Drilli	ng Coi	ntrac	ctor/R	ig:	2R Drilling/GT8		_ Drill	Date:	1/6/2	<u>5</u> H	ole Dia	ameter (in): 8
Depth (ft)	Elevation (ft)	Water Level	Graphic Log	USCS	DESCRIPTION	Sample Designation	Dry Unit Weight (pcf)	Moisture Content (%)	Fines (%)	Sample Type	Field Blow Count	Remarks
0	- 625				9.5" AC; no base							
1 2	- 624 - 623			SM	Artificial Fill (Af); Silty sand with gravel (SM); light gray brown, slightly moist, ifne to medium sand, fine gravel							Bulk 1: 0-5' Moisture: 14.6%
3	- 622 - 621				Colluvium (Qc); Clayey sand with gravel (SC); medium red brown, moist, loose, fine sand, fine gravel	R1	114.0	6.4	-	MC	20 20 15	
5	- 620			SC							4 4	
7	- 618					R2	97.0	12.6	-	MC	8	
8	- 617				Landslide Deposits (Ols);	-						
10	- 615				Sandy silt (ML) matrix; light brown, moist, stiff, fine sand, some fine gravel, trace clay						13	
11	- 614 - 613					R3	118.7	11.5	-	MC	12 13	
13	- 612			ML								
14 15	- 611 - 610				choppy, difficult drilling, at 15 feet (rock						27	
16	- 609				fragments, little to no matrix in cuttings)	R4	106.1	6.7	-	MC	27 27 19	
17-	- 608											
18	- 607 - 606				Silty sand (SM); light brown to light yellow brown, moist, dense to very dense, with hard sandstone fragments							
20	- 605					R5	109.8	6.6	-	MC	50/4"	
21	- 604			SM								
22	- 603											
23	- 602		0.0000									
24	- 601				Gravelly clay (CL); light brown, moist, dense,							
25	- 600				fine to coarse gravel, clast-supported						34	
26	- 599					R6	112.5	11.0	-	MC	36 38	
27	- 598			GC								
28	- 597											
29	- 596											
30-		ا ا									-	

COTTON, SHIRES AND ASSOCIATES, INC. LOG OF EXPLORATORY DRILLING												
Projec	ct:	V	/CPW	'A - Ye	erba Buena Road Distress Logged By:	EP	<u>B</u> P1	roject l	Numbe	er: <u>SC</u>	6164	Boring: B-1
Locat	ion:				MP 1.94	Eleva	tion (ft):62	<u>25 </u> V	Veathe	er:(Clear/warm
Drilli	ng Coi	ntrac	ctor/R	ig:	2R Drilling/GT8		_ Drill	Date:_	1/6/2	5_H	ole Dia	ameter (in): <u>8</u>
Depth (ft)	Elevation (ft)	Water Level	Graphic Log	NSCS	DESCRIPTION	Sample Designation	Dry Unit Weight (pcf)	Moisture Content (%)	Fines (%)	Sample Type	Field Blow Count	Remarks
30-	- 595					R7	-	-	-	MC	33 50/2"	
31	- 594			GC							20/2	
32	- 593											
33	- 592				Siltstone/Shale matrix; gray to light gray							
34	- 591				brown, moist, pervasively fractured, no obervable bedding							
35 -	- 590					S1	-	-	-	SPT	31	
36	- 589										30/3	
37	- 588											
38	- 587											
39	- 585											
41	- 584					S2	-	-	-	SPT	45 50/3"	
42	- 583											
43	- 582											
44	- 581											
45	- 580				very slow drilling, at 45 feet	S3	-	-	-	SPT	50/3"	
46	- 579											
47 -	- 578					S4	-	-	-	SPT	50/1"	
48 -	- 577				Auger Refusal at 47'-2" No groundwater encountered.							
49 -	- 576				Boring backfilled with cuttings and hydrated cement, capped with quickset concrete dyed							
50	- 575				black.							
51	- 574											
52	- 573											
54	- 572											
55	- 570											
56	- 569											
57	- 568											
58	- 567											
59	- 566											
60-												

COTTON, SHIRES AND ASSOCIATES, INC. LOG OF EXPLORATORY DRILLING												
Projec	ct:	V	/CPW	/A - Ye	erba Buena Road Distress Logged By	EP	<u>B</u> P1	roject l	Numbe	er: <u>SC</u>	6164	Boring: B-2
Locat	ion:				MP 1.94	Eleva	tion (ft):62	<u>0</u>	Weathe	er:(Clear/warm
Drilli	ng Co	ntra	ctor/R	ig:	2R Drilling/GT8		_ Drill	Date:	1/6/2	<u>5</u> H	ole Dia	ameter (in): 8
Depth (ft)	Elevation (ft)	Water Level	Graphic Log	USCS	DESCRIPTION	Sample Designation	Dry Unit Weight (pcf)	Moisture Content (%)	Fines (%)	Sample Type	Field Blow Count	Remarks
0-	- 620				7" AC; no base							
1 2	- 619 - 618			ML	Artificial Fill (Af); Sandy silt with gravel (SM); light gray brown, slightly moist, ifne to medium sand, fine gravel							
3 4 5	- 617 - 616 - 615		0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		Landslide Deposits (Qls); Sandy silt (ML); light yellowish brown, slightly moist, very stiff, with scattered to abundant siltstone fragments, varies from clast to matrix supported						9	
6 7	- 614 - 613				difficult drilling, from about 6 to 15 feet	R1	105.3	4.8	14.7	MC	17 23	
8 9 10	- 612 - 611 - 610				continued difficult drilling, at 10 feet						9	
11 12	- 609 - 608			ML		R2	127.0	6.4	_	MC	19 50/5"	
13 14 15	- 607 - 606 - 605										5 40	
16 17 18	- 604 - 603 - 602				buff, cemented sandstone fragments, and light gray to light brown siltstone fragments, closely fractured, caliche-lined, at 16 feet	R3	-	2.8	-	MC	50/5"	
19 20 21	- 601 - 600 - 599				light grav siltstone fragments in silty						6 39	
22	- 598				sand/sandy silt matrix, clast-supported, dense, very difficult drilling, from 21 to 23 feet	R5	128.9	2.1	-	MC	48	
23	- 597		• • • • • •			S 1	-	-	-	SPT	50/3"	
24	- 596				Total Depth 23'-3"							
25 26	- 595 - 594				No groundwater encountered. Boring backfilled with cuttings and hydrated cement, capped with quickset concrete dyed black.							
27	- 593											
28	- 592											
29	- 591											
30-												

COTTON, SHIRES AND ASSOCIATES, INC. LOG OF EXPLORATORY DRILLING														
Projec	:t:	١	/CPW	A - Ye	erba Buena Road Distress Logged By:	EP	<u>B</u> Pı	roject l	Numbe	er: <u>SC</u>	6164	Borin	g: <u>B</u>	-3
Locat	ion:				MP 2.96	Eleva	tion (ft):98	<u>33</u>	Veathe	er: <u>S</u>	unny/v	vindy	
Drillin	ng Co	ntrac	ctor/R	ig:	2R Drilling/GT8		_ Drill]	Date:	1/13/2	<u>5</u> H	ole Dia	meter	(in):	8
Depth (ft)	Elevation (ft)	Water Level	Graphic Log	USCS	DESCRIPTION	Sample Designation	Dry Unit Weight (pcf)	Moisture Content (%)	Fines (%)	Sample Type	Field Blow Count	R	emarks	
0-	- 983				8" AC; no base									
1 2	- 982 - 981			ML	Artificial Fill (Af); Clayey silt (ML); light brown, slightly moist, stiff, with higly fractured shale fragments									
3	- 980 - 979				Lower Topanga Formation (Ttlc); Sandstone: medium gray brown, moderately weathered, moderately hard, highly fractured,	R1	112.2	2.4	-	MC	22 50/3"			
5	- 978				shale		1			1.0				
6	- 977			Ttlc		R2	115.5	4.5	-	мс	50/5"			
7	- 976													
8 =	- 975													
9-	- 974													
10	- 973					S1	-	4.8	-	SPT	50/5.5"			
11 12	- 972 - 971				Total Depth 10'-6" No groundwater encountered. Boring backfilled with cuttings and hydrated									
13	- 970				cement, capped with quickset concrete dyed black.									
14	- 969													
16	- 967													
17	- 966													
18	965													
19	- 964													
20	- 963													
22	- 961													
23	- 960													
24	- 959													
25	- 958													
26	- 957													
27 -	- 956													
28	- 955													
29	- 954													
50-														

					COTTON, SHIRES AND ASSO LOG OF EXPLORATORY DI	OCIA RILLIN	ATES NG	, INO	С.			
Proje	ct:	١	/CPW	'A - Ye	erba Buena Road Distress Logged By:	EP	<u>B</u> Pı	oject l	Numbe	er: <u>SC</u>	6164	Boring: <u>B-4</u>
Locat	tion:				MP 2.96	Eleva	tion (ft):97	<u>'9</u> V	Weathe	er: <u>S</u>	unny/windy
Drilli	ng Coi	ntrac	ctor/R	ig:	2R Drilling/CME 55 Track		_Drill	Date:	1/13/2	<u>25</u> Н	ole Dia	meter (in): <u>8</u>
Depth (ft)	Elevation (ft)	Water Level	Graphic Log	USCS	DESCRIPTION	Sample Designation	Dry Unit Weight (pcf)	Moisture Content (%)	Fines (%)	Sample Type	Field Blow Count	Remarks
0	- 979		00.00		8" AC; no base							
1- 2-	- 978 - 977		0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	ML	Artificial Fill (Af); Clayey silt (ML); light brown, slightly moist, stiff, with higly fractured shale fragments						6	Bulk 1: 0-5' Moisture: 15.1%
3	- 976				Lower Topanga Formation (Ttlc);	R1	115.6	8.6		MC	6	
4	- 975				moderately weathered, moderately hard, moderately fractured		115.0	0.0		ine		
5	- 974 - 973										17 22	
7	- 972				slwo, difficult drilling, from 7 to 15 feet	R2	-	-	-	MC	25	
8-	- 971											
9-	- 970											
10	- 969					R3	-	-	-	MC	50/2"	
11	- 968			T .1								
12	- 967			Ttle								
13	- 966											
14	- 965											
15	- 964										7	
16-	- 963				slightly hard, highly oxidized, at 16 feet	S1	-	8.3	-	SPT	38	
17- 19	- 962											
10	- 960											
20	- 959				light gray, laminated, slightly to moderately	R4	115.7	10.2	-	MC	50/3"	
21	- 958	ſ			hard, closely fractured							
22	- 957				Total Depth 20'-3" No groundwater encountered.							
23	- 956				Boring backfilled with cuttings and hydrated cement, capped with quickset concrete dyed							
24	- 955				black.							
25	- 954											
26	- 953											
27	- 952											
28-	- 951											
29	- 950											
30-												

					COTTON, SHIRES AND ASS LOG OF EXPLORATORY D	OCIA DRILLIN	ATES	, IN	C.			
Projec	et:	V	VCPW	A - Y	erba Buena Road Distress Logged By	v: <u>EP</u>	B P	roject]	Numbe	er: <u>SC</u>	6164	Boring: B-5
Locat	ion:				MP 2.96	_ Eleva	ation (ft):97	76	Weathe	er: S	unny/windy
Drilli	ng Co	ntra	ctor/R	ig:	2R Drilling/CME 55 Track		_ Drill	Date:	1/13/2	<u>25</u> Н	ole Dia	meter (in): 8
Depth (ft)	Elevation (ft)	Water Level	Graphic Log	USCS	DESCRIPTION	Sample Designation	Dry Unit Weight (pcf)	Moisture Content (%)	Fines (%)	Sample Type	Field Blow Count	Remarks
0	- 976				9" AC; no base							
1 2 3	- 975 - 974 - 973			ML	Artificial Fill (Af); Clayey silt (ML); light brown, slightly moist, stiff, with higly fractured shale fragments Lower Topanga Formation (Ttlc); Shale/Siltstone: light gray, moderately weathered, moderately hard, moderately	R1	109.4	3.6	53.5	MC	33 40 42	
4 -	- 972				fractured, interbedded fine grained cemented sandstone (very difficult drilling)							
	- 971			Ttlc		S 1	-	3.4	-	SPT	10 50/3"	
6 7 7 8	- 970 - 969 - 968											
9-	- 967											
10 11 12	- 966 - 965 - 964				Auger Refusal at 9' No groundwater encountered. Boring backfilled with cuttings and hydrated cement, capped with quickset concrete dyed black.							
13 14	- 963 - 962											
15	- 961											
16	- 960											
17 18	- 959 - 958											
19	- 957											
20	- 956											
21	- 955											
22	- 954											
23	- 953											
24	- 952											
25	- 951											
26	- 950											
27	- 949											
28	- 948											
29	- 947											
30-												

Г

					COTTON, SHIRES AND ASS LOG OF EXPLORATORY E	SOCIA DRILLIN	ATES NG	, INO	С.			
Proje	ct:	V	VCPW	/A - Ye	erba Buena Road Distress Logged By	y: <u>EP</u>	<u>B</u> P	roject l	Numb	er: <u>SC</u>	26164	Boring: B-6
Loca	tion:				MP 2.61	_ Eleva	tion (ft):85	<u>59</u>	Weath	er: <u>S</u>	unny/windy
Drilli	ng Co	ntra	ctor/R	.ig:	2R Drilling/CME 55 Track		_ Drill	Date:_	1/13/2	<u>25</u> Н	ole Dia	ameter (in): <u>8</u>
Depth (ft)	Elevation (ft)	Water Level	Graphic Log	USCS	DESCRIPTION	Sample Designation	Dry Unit Weight (pcf)	Moisture Content (%)	Fines (%)	Sample Type	Field Blow Count	Remarks
0-	859 858				17" AC; no base							
2- 3- 4-	- 857 - 856 - 855			ML	Artificial Fill (Af); Sandy silt (ML); light to medium brown, moist, medium stiff, fine sand, with highly fractured siltstone fragmentsColluvium (Qc)/Landslide Deposits (Qls);	R1	122.8	4.4	-	MC	6 6 7	
5-	- 854 - 853		0.0 0.0 0 0.0 0.0 0 0.0 0.0 0		Sandy silt (ML); medium brown, slightly moist, stiff, fine sand, with scattered to abundant fine gravel occasional rootlets		120.(9 10	
7-	852				veru difficult drilling, to about 15 feet	R2	120.6	7.6	-	мс	12	
8- 9- 10-	851 850 849										0	
11-	- 848					R3	-	-	-	MC	8 7 10	
12 13	- 847 - 846			МТ								
14- 15-	- 845 - 844			IVIL							15	
16– 17–	- 843 - 842					R4	118.2	11.6	-	MC	21 22	
18 19	- 841 - 840											
20-	839				less matrix (occasional pockets), highly						12 18	
22	- 837				fractured siltstone and cemented shale, at 21 feet	R5	117.4	9.6	-	MC	22	
23- 24-	836 - 835		0.00.00 0.00.00 0.00.00 0.00.00		Lauran Tananga Farmatian (Ttila).							
25-	- 834				Shale/Siltstone: light gray, moderately weathered, moderately hard, moderately	R6	-	-	-	MC	50/2"	
26-	833			Ttle	fractured							
28	- 831			1 the								
29-	- 830					<u>S1</u>				SPT	50/1"	
30-	829 828				Total Depth 30'	51				Jori	1 30/1	
32- 33- 34-	827 826 825				No groundwater encountered. Boring backfilled with cuttings and hydrated cement, capped with quickset concrete dyed black.							
35-	1											

Г

					COTTON, SHIRES AND ASS LOG OF EXPLORATORY D	OCIA RILLIN	ATES NG	, INO	С.			
Projec	ct:	V	/CPW	'A - Ye	erba Buena Road Distress Logged By	EP	B Pi	roject l	Numbe	er:_SC	6164	Boring: B-7
Locat	ion:				MP 2.61	Eleva	tion (ft):85	<u>52</u>	Weath	er: <u>S</u>	unny/windy
Drilli	ng Coi	ntrac	ctor/R	ig:	2R Drilling/CME 55 Track		_ Drill	Date:	1/13/2	<u>25</u> Н	ole Dia	meter (in): 8
Depth (ft)	Elevation (ft)	Water Level	Graphic Log	USCS	DESCRIPTION	Sample Designation	Dry Unit Weight (pcf)	Moisture Content (%)	Fines (%)	Sample Type	Field Blow Count	Remarks
0	- 852				14" AC; no base							
1-	- 851				Artificial Fill (Af):	-						
2	- 850				Sandy clay (CL) to Clayey sandy silt (ML) matrix: medium to dark gray brown: moist.							
3	- 849				medium stiff, fine sand, with waethered silfstone fragments						3 4	
4-	- 848					R1	107.7	15.5	-	MC	5	
5-	- 847										7	
6	- 846			CL	light gray to light brown weather claystone/siltstone fragments (no matrix), at 6	R2	119.1	11.6	-	MC	11 12	
7_	- 845			CL	feet							
8 -	- 844											
9-	- 843											
10	- 842										3	
11	- 841				increased siltstone fragments, loose, piece of thin gauge wire, at 11 feet	R3	108.7	7.1	-	MC	14 11	
12	- 840		* <u>/.o: */.o:</u> 		Lower Topanga Formation (Ttlc);	-						
13	- 839				Shale/Silistone: light to medium gray, moderately weathered, moderately hard,							
14-	- 838				semi-silicious							
15	- 837					R4	116.0	4.7	-	MC	50/4"	
16	- 836			Ttle								
1/	- 835 824											
10	- 833											
20	- 832					R5				MC	50/4"	
21	- 831	ł			Total Donth 2012"	KJ	-	-	-	WIC	50/4	
22	- 830				No groundwater encountered. Boring backfilled with suttings and hydrotod							
23	- 829				cement, capped with quickset concrete dyed							
24	- 828											
25	- 827											
26	- 826											
27	- 825											
28	- 824											
29	- 823											
30-												

					COTTON, SHIRES AND ASS LOG OF EXPLORATORY D	OCIA RILLI	ATES	S, INO	C.				
Projec	et:		VCPW	/A - Y	erba Buena Road Distress Logged By	r: <u>EP</u>	<u>B</u> P	roject]	Numbe	er: <u>SC</u>	26164	Boring:_	B-8
Locat	ion:				MP 2.61	_ Eleva	ation (ft):84	16 V	Weath	er: S	unny/win	dy
Drillin	ng Co	ntra	ctor/R	.ig:	2R Drilling/CME 55 Track		_ Drill	Date:	1/14/2	<u>25</u> Н	ole Dia	ameter (in):_8
Depth (ft)	Elevation (ft)	Water Level	Graphic Log	USCS	DESCRIPTION	Sample Designation	Dry Unit Weight (pcf)	Moisture Content (%)	Fines (%)	Sample Type	Field Blow Count	Rema	ırks
	- 846				9.5" AC; no base								
	- 845 - 844 - 843			SM	Artificial Fill (Af); Silty sand (SM); gray brown, slightly moist, medium dense, fine grained, with scattered small siltstone fragments						10		
	- 842				Lower Topanga Formation (Ttlc); Shale/Siltstone: light gray brown to light	R1	117.9	7.7	15.7	MC	11		
5	- 841				brown, moderately weathered, moderately hard, moderately fractured, thinly bedded, oxidized						7		
6	- 840				UNRIZED	R2	-	_	-	MC	13 46		
7	- 839			Ttlc	difficult drilling, at 7 feet								
8-	- 838 - 837												
	- 836		 								34		
	- 835				light gray, decreased fracturing, laminated to thinly bedded, diffcult drilling, transitions to	S1	-	4.8	-	SPT	50		
12	- 834			1	hard cemented sandstone	<u> </u>	-	-	-	SPI	50/1.5		
	- 833 - 832 - 831 - 830				Total Depth 12'-1.5" No groundwater encountered. Boring backfilled with cuttings and hydrated cement, capped with quickset concrete dyed black.								
17	- 829												
18	- 828												
	- 827												
20	- 825												
22	- 824												
23	- 823												
24	- 822												
25	- 821												
26	- 820												
27	- 819												
$\begin{bmatrix} 28 \\ -20 \end{bmatrix}$	- 818 - 817												
30	01/												
		1											

					COTTON, SHIRES AND ASS LOG OF EXPLORATORY E	SOCIA DRILLIN	ATES ∖G	, INO	С.			
Proje	ct:	V	/CPW	/A - Ye	erba Buena Road Distress Logged By	/: <u>EP</u>	<u>B</u> P1	roject l	Numbe	er: <u>SC</u>	6164	Boring: <u>B-9</u>
Locat	ion:				MP 0.93	tion (ft):30	0	Weathe	er: S	unny/breezy	
Drilli	ng Coi	ntrac	ctor/R	ig:	2R Drilling/CME 55 Track		_ Drill	Date:	1/14/2	<u>25</u> Н	ole Dia	meter (in): 8
Depth (ft)	Elevation (ft)	Water Level	Graphic Log	USCS	DESCRIPTION	Sample Designation	Dry Unit Weight (pcf)	Moisture Content (%)	Fines (%)	Sample Type	Field Blow Count	Remarks
0-	- 300				13" AC; no base							
1 2 3 4	- 299 - 298 - 297 - 296	, , , , , , , , , , , , , , , , , , ,		ML	Artificial Fill (Af); Sandy silt (ML); light to medium brown, slightly moist, stiff, with siltstone fragments, clast supported		108.0	7.6		MC	10 14 14	Bulk 1: 0-5' Moisture: 3.3%
5	- 295 - 294			ML	Natural Soil (Qs); Sandy silt (ML); medium brown, moist, stiff, with siltstone fragments, occasional rootlets		103.2	12.0	_	мс	10 14 12	
7 8 9	- 293 - 292 - 291				Colluvium (Qc)/Landslide Deposits (Qls); Claey silty sand (SC); light brown, moist, medium dense, with abundant fine gravel, varies from clast to matrix supported, heavily oxidized							
10-	- 290 - 289					R3	-	-	-	MC	25 12 14	
12 13 14 15	- 288 - 287 - 286 - 285	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		SC							10	
16 17 18	- 284 - 283 - 282				relatively lighter drilling, from about 16.5 to 20 feet	<u>S1</u>	-	-	-	SPT	4	
10 19 20	- 281 - 280										12	
21	- 279					R4				MC	10	
22	- 278						_	_	-	MC	5	
23	- 277				pervasively fractured, highly oxidized and						13 19	
24	- 276					R5	127.8	7.3	-	MC	40	
25	- 275				Lower Topanga Formation (Ttlc); Shale/Siltstone: light gray, moderately						16	
26	- 274		 		weathered, moderately hard, lightly fractured, thinly bedded, oxidized	R6	118.0	3.6	-	MC	43 50/4	
27	- 273			Ttlc								
28	- 272											
29	- 271											
30-					l	I	I	I		I	I I	

					COTTON, SHIRES AN LOG OF EXPLOR	ND ASSO ATORY DR	DCIA RILLIN	ATES √G	, INO	Ξ.			
Projec	et:	V	CPW	'A - Ye	erba Buena Road Distress	Logged By:	EP	<u>B</u> Pı	roject I	Numbe	er: <u>SC</u>	6164	Boring: <u>B-9</u>
Locat	ion:				MP 0.93		Eleva	tion (ft):30	<u> </u>	Veathe	er: S	unny/breezy
Drilli	ng Co	ntrac	tor/R	ig:	2R Drilling/CME 55 T	rack		_Drill	Date:	1/14/2	2 <u>5</u> He	ole Dia	umeter (in): 8
Depth (ft)	Elevation (ft)	Water Level	Graphic Log	USCS	DESCRIPTION		Sample Designation	Dry Unit Weight (pcf)	Moisture Content (%)	Fines (%)	Sample Type	Field Blow Count	Remarks
30-	- 270	ĿĿ		Ttle		I					L		
$\begin{array}{c} 30 \\ 31 \\ 32 \\ 33 \\ 34 \\ 35 \\ 36 \\ 37 \\ 38 \\ 39 \\ 40 \\ 41 \\ 42 \\ 43 \\ 44 \\ 45 \\ 46 \\ 47 \\ 48 \\ 49 \\ 49 \\ \end{array}$	- 270 - 269 - 268 - 267 - 266 - 265 - 264 - 263 - 262 - 261 - 260 - 259 - 258 - 257 - 256 - 255 - 254 - 253 - 252 - 251			Ttle	Total Depth 30'-4" No groundwater encountered. Boring backfilled with cuttings and hydr cement, capped with quickset concrete of black.	rated lyed							
50	- 250												
51	- 249												
52	- 248												
53	- 247												
55	- 240												
56	- 244												
57	- 243												
58	- 242												
59	- 241												
60-													

٦

					COTTON, SHIRES AND ASS LOG OF EXPLORATORY I	SOCIA DRILLIN	ATES NG	, INO	С.					
Proje	ct:	V	/CPW	'A - Ye	erba Buena Road Distress Logged B	y: <u>EP</u>	<u>B</u> P1	roject l	Numbe	er: <u>SC</u>	6164	Boring: B-10		
Locat	ion:				MP 0.93	_ Eleva	tion (ft):29	<u>5</u> V	Weathe	er: <u>S</u>	unny/breezy		
Drilli	ng Coi	ontractor/Rig: 2R Drilling/CME 55 Track Drill Date: 1/14/25 Hole Diamete												
Depth (ft)	Elevation (ft)	Water Level	Graphic Log	USCS	DESCRIPTION	Sample Designation	Dry Unit Weight (pcf)	Moisture Content (%)	Fines (%)	Sample Type	Field Blow Count	Remarks		
0-	- 295				11.5" AC; no base									
1 2 3	- 294 - 293 - 292			SM	Artificial Fill (Af); Silty sand (SM); light to medium brown, slightly moist, loose, with abundant rock fragments, matrix supported	R1	108.2	7.6	_	MC	12 50/5"			
4-	- 291					_								
5	- 290				Sandy silt (ML); medium brown, moist, stiff, fine sand, trace clay, with abundant small						18 19			
7	- 289 - 288		0.000 0.0000 0.0000 0.0000 0.000000	ML	siltstone fragments, matrix supported	R2	-	-	-	MC	14			
8-	- 287													
9-	- 286				Lower Topanga Formation (Ttlc); Sandstone; buff, moderately weathered,									
10	- 285				moderately hard, highly fractured						18			
11	- 284					R3	116.6	3.4	-	MC	30 36			
12	- 283			Ttlc										
13	- 282													
14-	- 281													
15	- 280 - 270				light brown, finre grained, slightly to moderately hard, at 15 feet	S1	-	7.9	-	MC	13 50/5.5"			
10	- 279													
18-	- 277				Siltstone: medium gray, moderately hard to hard, highly fractured, cemented, laminated to									
19	- 276			Ttlc	thinly bedded									
20-	- 275					DC	120.2	5.2		MC	37			
21	- 274					KS	120.2	5.2	-	MC	50/4"			
22	- 273				No groundwater encountered.									
23	- 272				cement, capped with quickset concrete dyed black									
24	- 271				onex.									
25	- 270													
26	- 269													
27	- 268 - 267													
20	- 266													
30-														

Rig ⁻ Test Loca	Type: <u>Hand Tools</u> COTTON, SHIRE ation: <u>Mile Post 0.93</u> EXPLORATORY TES ENGINEERING GEC	ES AND ASSOCIATES, INC. T PIT LOG No. <u>TP-04 & 05</u> DLOGIC DESCRIPTION	Project No: Date Logged: Logged By:	SC6164 1/21/25 EPB
af ₁ : af ₂ : Qc:	Silty sand to sandy silt matrix, light brown to tan, mottled, moderately of and loose, abundant bedrock fragments up to 5" across, scattered root Sandy silt to silty sand, brown to reddish brown, mottled, slightly moist rootlet Sandy silt, brown, medium dense, slightly moist to moist, very fine to m occasional rootlet	compact to compact, dry to slightly moist, ts and rootlets to moist, abundant bedrock fragments u nedium sand, abundant bedrock fragmen	upper 1' was distrub p to 5" across, occas ts up to 5" across,	ed ional
GRAP	HIC REPRESENTATION SCALE	: 1" = 2.5'		
	$\frac{\text{TP04}}{\text{Total Depth: 6-1/2'}}$ $\frac{1}{\text{Slope: } 35^{\circ} - 40^{\circ}}$ $\frac{1}{\text{-}}$ $\frac{1}{\text{-}$	$ \begin{array}{c} $	oth: 5' pe: 35° slope	

Rig Type: <u>Hand Tools</u>	COTTON, SHIRES AND ASSOCIATES, INC.	Project No:	SC6164
Location: Mile Post 1.94		Date Logged:	<u> </u>
		Logged Dy.	
	ENGINEERING GEOLOGIC DESCRIPTION		
af: Sandy silt to silty sand, light brow abundant bedrock clasts up to 6"	n to brown, mottled, slightly moist to moist, slightly compact to compact, very across, scattered roots and rootlets, scattered construction debris, occasion	[,] fine to medium sand, al rodent hole in upper	6"
GRAPHIC REPRESENTATION	SCALE: 1" = 2.5'		
	TP03 Total Depth: 5' Slope: 45° & steeper -		

Rig Type: <u>Hand Tools</u> Test Pit Location: <u>Mile Post 2.61</u>	EXPLORATORY TEST PIT LOG No. <u>TP-01 & 02</u>	Project No: <u>SC6164</u> Date Logged: <u>1/20/25</u> Logged By: <u>EPB</u>	
	ENGINEERING GEOLOGIC DESCRIPTION		
 af₁: Silty sand to sandy silt, light brow fragments, loose in the upper 6" af₂: Silty sand to sandy silt, brown, s slightly to moderately compact, s Qc: Sandy silt, brown to red brown, s Ttlc: Thinly bedded to laminated med are filled 	wn to brown, dry to slightly moist, very fine to medium sand, abundant gra increasing to moderately compact below that, occasional root & construc lightly moist to moist, very fine to medium sand, abundant gravel to cobble scattered rootlets, occasional fragment up to 18" across slightly moist to moist, medium dense, abundant bedrock fragments, poss lium gray siltstone/shale, moderately hard to hard, highly fractured, some	vel to cobble sized bedrock tion debris up to 18" across e sized bedrock fragments, ible clay binder fractures are open and some	
GRAPHIC REPRESENTATION	SCALE: 1" = 2.5'		
TP01 Total Depth: 4 Slope: 5 0- 1- 2- Ttlc 5- 5- Ttlc Fragment 5- Ttlc Fragment Ttlc Fragment Ttlc Fragment Ttlc Fragment	 5-1/4' 36° ① Bedding: N84W,22N ② Fissure: N11-12W, near-veand slightly irregular Ttic Fragment 8" 	TP02 Total Depth: 6' Slope: 45° -1 -2 af -3 -4 -5 -6	

APPENDIX B LABORATORY TESTING

APPENDIX B – LABORATORY TESTING

INTRODUCTION

Laboratory analyses performed for the project consisted of limited testing of the principal soil types sampled during the field investigation to evaluate index properties of subsurface materials. Laboratory tests were performed on selected driven ring or bulk soil samples to estimate engineering characteristics of the various earth materials encountered. Testing was performed in general accordance with ASTM Standards for Soil Testing, latest revision. Soil descriptions and the field and laboratory test results were used to assign parameters to the various materials at the site. Testing procedures are presented below, and results of the laboratory testing program are presented in this appendix, and the boring logs included in Appendix A.

Laboratory Moisture and Density Determinations

Moisture content and dry density determinations were performed on select driven ring samples collected to evaluate the natural water content and dry density of the various soils encountered in accordance with ASTM D7263. In addition, moisture contents were determined on select collected bulk samples in accordance with ASTM D2216. The results are presented on Table B-1 – Summary of Laboratory Test Results, and on the respective boring logs in Appendix A.

Grain Size Distribution

Four tests were performed to determine the amount of material in soils finer than the No. 200 Sieve in accordance with ASTM test method D1140. The results are presented in Table B-1 and in Figure B-1a – Grain Size Distribution Curves.

Atterberg Limits Tests

Atterberg limits tests were performed on four selected samples. Liquid and plastic limits were determined in accordance with standard test method ASTM D4318. The results are presented on Table B-1 and on Figure B-2 – Atterberg Limits' Results.

Direct Shear Tests

Multistage direct shear tests were performed on three representative driven ring samples to evaluate the shear strength of earth materials. The tests were performed in accordance with standard test method ASTM D3080. The results are presented on Table B-1 and on Figures B-3a and B-3c –Shear Test Diagram.

VCPWA – Yerba Buena Road Distress Page B-2

Consolidated Undrained Triaxial Tests

Four consolidated undrained triaxial compression tests were completed on representative driven samples to evaluate the strength of earth materials. Tests were performed in accordance with standard test method ASTM D4746. The results are presented on Figures B-4a through B-4d – Consolidated Undrained Triaxial Compression with Pore Pressure.

Maximum Unit Weight/Optimum Moisture Content Tests

Maximum unit weight and optimum moisture content tests were performed on two select samples of near surface onsite soils to assess their compaction characteristics. The tests were performed in accordance with ASTM D1557, and the results are presented on Table B-1 and on Figures B-5a and B-5b – Moisture-Density Relationship.

Soil Chemistry Tests/Corrosion Tests

A soil corrosion suite was performed on a select near surface sample to evaluate resistivity, pH, sulfate, and chloride. Results of the testing and a preliminary analysis of the corrosivity to reinforcement steel and concrete materials are presented on Table B-1 and are summarized in the main report.

TABLE B-1 SUMMARY OF LABORATORY TEST RESULTS

Boring	Depth	USCS	Moisture Content	In-Situ Moist Unit Weight	In-Situ Dry Unit Weight	Passing #200 Sieve	Atterbe LL	rg Limits PL	Peak Stree	Shear ngth	Maximum Ur Optimum Mois	iit Weight / ture Content	C	orrosio	on Potentia	1
No.	(feet)	Symbol	(%)	(pcf)	(pcf)	(%)	(%)	(%)	φ (deg)	c (psf)	Unit Weight	Moisture	Resistivity	pН	Chorides	Sulfates
											(pcf)	(%)	(ohm)		(%)	(%)
B-1	0-5		14.6								123.3	11.9				
B-1	3.5		6.4	121.3	114.0											
B-1	6.0		12.6	109.2	97.0				38	80						
B-1	11.0		11.5	132.4	118.7				36	80						
B-1	16.0		6.7	113.2	106.1											
B-1	20.0		6.6	117.0	109.8											
B-1	26.0		11.0	124.9	112.5											
B-2	6.0		4.8	110.4	105.3	14.7	28	18					3,100	6.3	0.009	0.001
B-2	11.0		6.4	135.1	127.0											
B-2	16.0		2.8													
B-2	21.0		2.1	131.6	128.9											
B-3	2.5		2.4	114.9	112.2											
B-3	5.0		4.5	120.7	115.5				32	300						
B-3	10.0		4.8													
B-4	0-5		15.1								121.2	13.3				
B-4	3.5		8.6	125.5	115.6											
B-4	16.0		8.3													
B-4	20.0		10.2	127.5	115.7											
B-5	3.5		3.6	113.3	109.4	53.5	19	17					6,200	6.3	0.008	0.001
B-5	5.5		3.4													
B-6	3.5		4.4	128.2	122.8											
B-6	6.0		7.6	129.8	120.6											
B-6	16.0		11.6	131.9	118.2											
B-6	21.0		9.6	128.7	117.4											

TABLE B-1 SUMMARY OF LABORATORY TEST RESULTS

Boring	Depth	USCS	Moisture Content	In-Situ Moist Unit Weight	In-Situ Dry Unit Weight	Passing #200 Sieve	Atterbe LL	rg Limits PL	Peak Shear Strength		Maximum Unit Weight / Optimum Moisture Content		Corrosion Potential			
No.	(feet)	Symbol	(%)	(pcf)	(pcf)	(%)	(%)	(%)	φ (deg)	c (psf)	Unit Weight (pcf)	Moisture (%)	Resistivity (ohm)	pН	Chorides (%)	Sulfates (%)
B-7	3.5		15.5	124.4	107.7											
B-7	6.0		11.6	132.9	119.1				21	200						
B-7	11.0		7.1	116.4	108.7											
B-7	15.0		4.7	121.5	116.0											
B-8	6.0		7.7	127.0	117.9	15.7	26	18					3,300	6.1	0.006	0.001
B-8	10.5		4.8													
B-9	0-5		3.3													
B-9	3.5		7.6	116.2	108.0											
B-9	6.0		12.0	115.6	103.2											
B-9	23.5		7.3	137.1	127.8				28	80						
B-9	26.0		3.6	122.2	118.0											
B-10	3.0		7.6	116.4	108.2											
B-10	11.0		3.4	120.6	116.6	30.3	25	15					2,700	6.4	0.008	0.001
B-10	16.0		7.9													
B-10	20.0		5.2	126.5	120.2				35	350						
TP-01	5.0		6.3	109.7	103.2				35	400						









APPENDIX C SEISMIC DESIGN PARAMETERS



No Address at This Location

ASCE Hazards Report

Standard: ASCE/SEI 7-16

Risk Category: II Soil Class:

C - Very Dense Soil and Soft Rock

Latitude: 34.065027 Longitude: -118.962648

Elevation: 297.3624947846284 ft (NAVD 88)







Ó



ġ

 2 S_a(g) vs T(s)



 2 S_a(g) vs T(s)

SC6164 MP 0.93 U.S. Geological Survey - Earthquake Hazards Program

Unified Hazard Tool

Please do not use this tool to obtain ground motion parameter values for the design code reference documents covered by the <u>U.S. Seismic Design Maps web tools</u> (e.g., the International Building Code and the ASCE 7 or 41 Standard). The values returned by the two applications are not identical.

Please also see the new <u>USGS Earthquake Hazard Toolbox</u> for access to the most recent NSHMs for the conterminous U.S. and Hawaii.

∧ Input	
Edition	Spectral Period
Dynamic: Conterminous U.S. 2014 (Peak Ground Acceleration
Latitude	Time Horizon
Decimal degrees	Return period in years
34.065027	475
Longitude	
Decimal degrees, negative values for western longitudes	
-118.962648	
Site Class	
537 m/s (Site class C)	





Summary statistics for, Deaggregation: Total

Deaggregation targets	Recovered targets				
Return period: 475 yrs Exceedance rate: 0.0021052632 vr^{-1}	Return period: 505.57764 yrs Exceedance rate: $0.0019779356 \text{ yr}^{-1}$				
PGA ground motion: 0.37143435 g					
Totals	Mean (over all sources)				
Binned: 100 %	m: 6.57				
Residual: 0 %	r: 15.19 km				
Trace: 0.16 %	ε ₀ : 0.68 σ				
Mode (largest m-r bin)	Mode (largest m-r-ɛ₀ bin)				
m: 6.11	m: 5.3				
r: 7.9 km	r: 8.8 km				
ε ₀ : 0.42 σ	ε ₀ : 1.24 σ				
Contribution: 8.3 %	Contribution: 2.92 %				
Discretization	Epsilon keys				
r: min = 0.0, max = 1000.0, ∆ = 20.0 km	ε0: [-∞2.5)				
m: min = 4.4, max = 9.4, Δ = 0.2	ε1: [-2.52.0)				
ε: min = -3.0, max = 3.0, Δ = 0.5 σ	ε2: [-2.01.5)				
	ε3: [-1.51.0)				
	ε4: [-1.00.5)				
	ε5: [-0.50.0)				
	ε6: [0.00.5)				
	ε7: [0.51.0]				
	ɛ8: [1.01.5]				
	ε9: [1.52.0)				

ε10: [2.0..2.5) **ε11:** [2.5..+∞]

Deaggregation Contributors

Source Set 💪 Source	Туре	r	m	٤ ₀	lon	lat	az	%
UC33brAvg_FM31	System							30.96
Malibu Coast alt 1 [9]		3.41	6.27	-0.21	118.933°W	34.048°N	124.17	6.73
Malibu Coast (Extension) alt 1 [0]		1.60	7.10	-0.88	118.964°W	34.052°N	185.20	4.11
Anacapa-Dume alt 1 [2]		8.61	7.33	-0.67	119.000°W	33.978°N	199.83	3.08
Simi-Santa Rosa [5]		19.95	7.10	1.02	118.999°W	34.241°N	350.31	2.17
Oak Ridge (Onshore) [0]		25.97	7.54	0.90	119.125°W	34.269°N	326.76	1.72
Sisar [1]		20.68	7.68	0.39	119.069°W	34.408°N	345.60	1.51
San Pedro Basin [11]		20.67	6.83	1.39	118.797°W	33.941°N	132.03	1.35
UC33brAvg_FM32	System							25.45
Anacapa-Dume alt 2 [5]		8.99	7.24	-0.66	118.998°W	33.974°N	197.80	4.73
Malibu Coast (Extension) alt 2 [0]		2.02	7.57	-1.02	118.965°W	34.055°N	189.64	3.33
Simi-Santa Rosa [5]		19.95	7.07	1.05	118.999°W	34.241°N	350.31	2.00
Malibu Coast alt 2 [4]		3.59	6.89	-0.54	118.933°W	34.051°N	120.06	1.98
Oak Ridge (Onshore) [0]		25.97	7.46	0.98	119.125°W	34.269°N	326.76	1.59
Sisar [1]		20.68	7.64	0.44	119.069°W	34.408°N	345.60	1.25
San Pedro Basin [11]		20.67	6.89	1.36	118.797°W	33.941°N	132.03	1.07
UC33brAvg_FM32 (opt)	Grid							21.80
PointSourceFinite: -118.963, 34.114		7.39	5.67	0.68	118.963°W	34.114°N	0.00	2.38
PointSourceFinite: -118.963, 34.114		7.39	5.67	0.68	118.963°W	34.114°N	0.00	2.38
PointSourceFinite: -118.963, 34.123		7.99	5.73	0.75	118.963°W	34.123°N	0.00	2.26
PointSourceFinite: -118.963, 34.123		7.99	5.73	0.75	118.963°W	34.123°N	0.00	2.26
PointSourceFinite: -118.963, 34.141		9.65	5.67	1.05	118.963°W	34.141°N	0.00	1.53
PointSourceFinite: -118.963, 34.141		9.65	5.67	1.05	118.963°W	34.141°N	0.00	1.53
PointSourceFinite: -118.963, 34.150		10.47	5.67	1.17	118.963°W	34.150°N	0.00	1.39
PointSourceFinite: -118.963, 34.150		10.47	5.67	1.17	118.963°W	34.150°N	0.00	1.39
UC33brAvg_FM31 (opt)	Grid							21.79
PointSourceFinite: -118.963, 34.114		7.40	5.65	0.71	118.963°W	34.114°N	0.00	2.60
PointSourceFinite: -118.963, 34.114		7.40	5.65	0.71	118.963°W	34.114°N	0.00	2.60
PointSourceFinite: -118.963, 34.123		8.04	5.70	0.78	118.963°W	34.123°N	0.00	2.32
PointSourceFinite: -118.963, 34.123		8.04	5.70	0.78	118.963°W	34.123°N	0.00	2.32
PointSourceFinite: -118.963, 34.141		9.53	5.70	1.00	118.963°W	34.141°N	0.00	1.41
PointSourceFinite: -118.963, 34.141		9.53	5.70	1.00	118.963°W	34.141°N	0.00	1.41
PointSourceFinite: -118.963, 34.150		10.36	5.70	1.13	118.963°W	34.150°N	0.00	1.20
PointSourceFinite: -118.963, 34.150		10.36	5.70	1.13	118.963°W	34.150°N	0.00	1.20



No Address at This Location

ASCE Hazards Report

Standard: ASCE/SEI 7-16

Risk Category: II Soil Class: C Very Dense **E**

Latitude: 34.075253 Longitude: -118.954545 Flevation: 624.1705485

C - Very Dense E Soil and Soft Rock

Elevation: 624.1705485955041 ft (NAVD 88)











2.0



Unified Hazard Tool

Please do not use this tool to obtain ground motion parameter values for the design code reference documents covered by the <u>U.S. Seismic Design Maps web tools</u> (e.g., the International Building Code and the ASCE 7 or 41 Standard). The values returned by the two applications are not identical.

Please also see the new <u>USGS Earthquake Hazard Toolbox</u> for access to the most recent NSHMs for the conterminous U.S. and Hawaii.

∧ Input	
Edition	Spectral Period
Dynamic: Conterminous U.S. 2014 (Peak Ground Acceleration
Latitude	Time Horizon
Decimal degrees	Return period in years
34.075253	475
Longitude	
Decimal degrees, negative values for western longitudes	
-118.954545	
Site Class	
537 m/s (Site class C)	





Summary statistics for, Deaggregation: Total

Deaggregation targets	Recovered targets			
Return period: 475 yrs Exceedance rate: 0.0021052632 yr ⁻¹ PGA ground motion: 0.37505034 g	Return period: 505.45355 yrs Exceedance rate: 0.00197%4212 yr ⁻¹			
Totals	Mean (over all sources)			
Binned: 100 k	m: 6.57			
Residual: 0 k	r: 15.27 m8			
Trace: 0.16 k	ε ₀ : 0.7 σ			
Mode (largest m-r bin)	Mode (largest m-r-ε₀ bin)			
m: 6.11	m: 6.13			
r: %11 n8	r: 4.22 n8			
ε ₀ : 0.45 σ	ε ₀ : i0.13 σ			
Contribution: %19 k	Contribution: 2.94 k			
Discretization	Epsilon keys			
r: 8 r∓, 0.0a8 x-, 1000.0a∆, 20.0 m8	ε0: [i∞i2.5)			
m: 8 № , 4.4a8 x- , 9.4aΔ , 0.2	ε1: [i2.5i2.0)			
ε: 8 m=, i3.0a8 x-, 3.0aΔ, 0.5 σ	ε2: [i2.0i1.5)			
	ε3: [i1.5i1.0)			
	ε4: [i1.0i0.5)			
	E5: [i0.50.0]			
	ε6: [0.00.5)			
	ει: [0.51.0]			

ε7: [0.5..1.0]
ε8: [1.0..1.5]
ε9: [1.5..2.0]
ε10: [2.0..2.5]

ε11: [2.5 .. +∞]

Deaggregation Contributors

Source Set 🕒 Source	Туре	r	m	٤ ₀	lon	lat	az	%
UC33brAvg_FM31	System							30.96
Malibu Coast alt 1 [] 4		3.9]	9.27	-0.1]	118.] 33°W	36.068°N	169.3(9.92
Malibu Coast Exnte) sio) 5alt 1 [04		2.73	7.11	-0.80	118.] (6°W	36.0(2°N	178.1(3.] 9
A) acapa-Dume alt 1 [24].(7	7.32	-0.(]	118.]]1°W	33.] 79°N	1] 9.82	2.] (
Simi-Sa) ta Rosa [(4		18.] 8	7.10	0.] 8	118.]]]°W	36.261°N	367.(0	2.3(
Oak Ridge EO) shore5[04		2(.((7.(3	0.8]	11] .12(°W	36.29] °N	326.0]	1.73
Sisar [14		20.28	7.98	0.39	11] .09] °W	36.608°N	366.11	1.((
Sa) Pedro Basi) [114		20.] 2	9.86	1.62	118.7] 7°W	33.] 61°N	13(.76	1.29
Oak Ridge ED) shore5[34		30.(6	7.(7	1.13	118.] 2] °W	36.392°N	6.1(1.06
UC33brAvg_FM32	System							2(.21
A) acapa-Dume alt 2 [(4].]0	7.2(-0.6]	118.]]8°W	33.] 76°N	1]].((6.39
Malibu Coast Exnte) sio) 5alt 2 [04		2.8]	7.(7	-1.00	118.] (6°W	36.0(6°N	178.8]	3.32
Simi-Sa) ta Rosa [(4		18.] 8	7.09	1.01	118.]]]°W	36.261°N	367.(0	2.18
Malibu Coast alt 2 [64		3.78	9.8]	-0.(8	118.] 33°W	36.0(1°N	163.9(2.01
Oak Ridge EO) shore5[04		2(.((7.69	0.] 8	11] .12(°W	36.29] °N	326.0]	1.91
Sisar [14		20.28	7.96	0.61	11] .09] °W	36.608°N	366.11	1.28
Sa) Pedro Basi) [114		20.] 2	9.] 0	1.38	118.7] 7°W	33.] 61°N	13(.76	1.01
UC33brAvg_FM31	Grid							22.13
Poi) tSourceFi) ite: -118.] ((, 36.12(7.3]	(.99	0.71	118.] ((°W	36.12(°N	0.00	(.2(
Poi) tSourceFi) ite: -118.] ((, 36.12(7.3]	(.99	0.71	118.] ((°W	36.12(°N	0.00	(.2(
Poi) tSourceFi) ite: -118.] ((, 36.191		10.30	(.72	1.12	118.] ((°W	36.191°N	0.00	2.30
Poi) tSourceFi) ite: -118.] ((, 36.191		10.30	(.72	1.12	118.] ((°W	36.191°N	0.00	2.30
Poi) tSourceFi) ite: -118.] ((, 36.209		13.6]	9.06	1.28	118.] ((°W	36.209°N	0.00	1.17
Poi) tSourceFi) ite: -118.] ((, 36.209		13.6]	9.06	1.28	118.]((°W	36.209°N	0.00	1.17
UC33brAvg_FM32	Grid							22.02
Poi) tSourceFi) ite: -118.] ((, 36.12(7.37	(.9]	0.98	118.] ((°W	36.12(°N	0.00	6.] (
Poi) tSourceFi) ite: -118.] ((, 36.12(7.37	(.9]	0.98	118.] ((°W	36.12(°N	0.00	6.] (
Poi) tSourceFi) ite: -118.] ((, 36.191		10.66	(.98	1.17	118.] ((°W	36.191°N	0.00	2.(7
Poi) tSourceFi) ite: -118.] ((, 36.191		10.66	(.98	1.17	118.] ((°W	36.191°N	0.00	2.(7
Poi) tSourceFi) ite: -118.] ((, 36.209		13.67	9.0(1.27	118.] ((°W	36.209°N	0.00	1.19
Poi) tSourceFi) ite: -118.] ((, 36.209		13.67	9.0(1.27	118.] ((°W	36.209°N	0.00	1.19



No Address at This Location

ASCE Hazards Report

Standard: ASCE/SEI 7-16

Latitude:

Risk Category: II Soil Class:

C - Very Dense Soil and Soft Rock

Longitude: -118.950912

Elevation: 872.3554114389942 ft (NAVD 88)

34.082709





Site Soil Class: Results:	C - Very Dense		
S _s :	1.476	S _{D1} :	0.512
S ₁ :	0.518	T _L :	8
F _a :	1.2	PGA :	0.634
F _v :	1.482	PGA M :	0.761
S _{MS} :	1.771	F _{PGA} :	1.2
S _{M1} :	0.767	l _e :	1
S _{DS} :	1.181	C _v :	1.195
Seismic Design Catego	Response Spectrum	12	Design Response Spectrum









SC6164 MP 2.61 U.S. Geological Survey - Earthquake Hazards Program

Unified Hazard Tool

Please do not use this tool to obtain ground motion parameter values for the design code reference documents covered by the <u>U.S. Seismic Design Maps web tools</u> (e.g., the International Building Code and the ASCE 7 or 41 Standard). The values returned by the two applications are not identical.

Please also see the new <u>USGS Earthquake Hazard Toolbox</u> for access to the most recent NSHMs for the conterminous U.S. and Hawaii.

∧ Input	
Edition	Spectral Period
Dynamic: Conterminous U.S. 2014 (Peak Ground Acceleration
Latitude	Time Horizon
Decimal degrees	Return period in years
34.052708	479
Longitude	
Decimal degrees, negative values for western longitudes	
-115.890812	
Site Class	
937 m/s (Site class C)	





Summary statistics for, Deaggregation: Total

Deaggregation targets	Recovered targets
Return period: 475 yrs Exceedance rate: 0.0021052632 yr ⁻¹ PGA ground motion: 0.37451g01 9	Return period: 502.114% yrs Exceedance rate: 0.001%/1575g yr ⁻¹
Totals	Mean (over all sources)
Binned: 100 k	m: 6.57
Residual: 0 k	r: 15.52 n8
Trace: 0.16 k	ε ₀ : 0.72 σ
Mode (largest m-r bin)	Mode (largest m-r-ɛ₀ bin)
m: 6.11	m: 6.12
r: g.45 n8	r: 5.4g n8
ε ₀ : 0.4%σ	ε ₀ : 0.15 σ
Contribution: 7.% k	Contribution: 2.% k
Discretization	Epsilon keys
r: 8 in = 0.0, 8 ax = 1000.0, ∆ = 20.0 m8	ε0: [-∞2.5)
m: 8 in = 4.4, 8 ax = %4, Δ = 0.2	ε1: [-2.52.0)
ε: 8 in = -3.0, 8 ax = 3.0, Δ = 0.5 σ	ε2: [-2.01.5)
	ε3: [-1.51.0)
	ε4: [-1.00.5)
	ε5: [-0.50.0]
	E0: [U.U U.S)
	CI • [0.J 1.0]

ε8: [1.0..1.5) **ε9:** [1.5..2.0) **ε10:** [2.0..2.5) **ε11:** [2.5..+∞]

Deaggregation Contributors

Source Set 😝 Source	Туре	r	m	٤ ₀	lon	lat	az	%
UC33brAvg_FM31	System							30.30
M96abl iCu9sti96ti1i o[].42	7.4-	80.14	11033°W	3] .0] - °N	127.2]	7.41
M96abl iCu9sti(Extensaun)i96ti1i 0[3.2]	5.13	80.54	11o2] °W	3] .024°N	1-].12	3.50
An9c9p98Dl mei9&i1i 4[10.4]	5.34	80.2]	11oo1°W	33.o57°N	105.10	42
SamaS9nt9iRus9i 2[147	5.0o	0.03	11000°W	3].4]1°N	3] 2.00	4.2]
09kiRadgei(Onshure)i 0[42.17	5.23	0 5	110.142°W	3] .470°N	344.] 3	1.5-
Sæ9ri 1[10.00	5.7-	0.33	110.070°W	3] .] 0- °N	3] 3.4-	1.20
S9niPedruiB9sani 11[41.40	72	1.]]	11505°W	33.o] 1°N	135.02	1.40
O9kiRadgei(Onshure)i 3[40.5]	5.25	1.00	11040°W	3].374°N	3.72	1.11
UC33brAvg_FM34	System							42.4-
An9c9p98Dl mei9&i4i 2[10.24	5.42	80.30	11o- o°W	33.o54°N	102.51].0-
M96bl iCu9sti(Extensaun)i96ti4i 0[3.71	5.25	80.00	11o2] °W	3] .02] °N	1-2.15	3.4-
SamaS9nt9iRus9i 2[147	5.07	0.07	11000°W	3].4]1°N	3] 2.00	4.37
M96abl iCu9sti96ti4i][].45	7 o	80.25	11o33°W	3].021°N	12] 0	1.00
09kiRadgei(Onshure)i 0[42.17	5.] 7	0.07	110.142°W	3] .470°N	344.] 3	1.77
Sæ9ri 1[10.00	5.7]	0.3-	110.070°W	3].]0-°N	3] 3.4-	1.34
UC33brAvg_FM31i(upt)	Grad							44.3-
PuantSul rceFanate:i811021,i3] .143		7.5-	2.73	0.74	11o21°W	3].143°N	0.00	4.00
PuantSul rceFarate:i811021,i3] .143		7.5-	2.73	0.74	11o21°W	3].143°N	0.00	4.00
PuantSul rceFarate:i811021,i3] .134		5.3-	2.75	0.50	11o21°W	3].134°N	0.00	4.7o
PuantSul rceFarate:i811021,i3] .134		5.3-	2.75	0.50	11o21°W	3].134°N	0.00	4.7o
PuantSul rceFarate:i811021,i3] .155		11.07	2.5]	1.40	11o21°W	3].155°N	0.00	1 5
PuantSul rceFarate:i811021,i3] .155		11.07	2.5]	1.40	11o21°W	3].155°N	0.00	1 5
PuantSul rceFarate:i811021,i3] .40]		145	2.05	1.42	11o21°W	3] .40] °N	0.00	1.4]
PuatSul rceFate:i811o21,i3] .40]		14 5	2.05	1.42	11o21°W	3].40]°N	0.00	1.4]
UC33brAvg_FM34i(upt)	Grad							44.03
PuantSul rceFarate:i811021,i3] .143		7.5-	2.72	0.70	11o21°W	3].143°N	0.00	4.54
PuantSul rceFanate:i811021,i3] .143		7.5-	2.72	0.70	11o21°W	3].143°N	0.00	4.54
PuantSul rceFarate:i811021,i3] .134		5.32	2.50	0.75	11o21°W	3].134°N	0.00	4.71
PuantSul rceFarate:i811021,i3] .134		5.32	2.50	0.75	11o21°W	3].134°N	0.00	4.71
PuantSul rceFarate:i&11o21,i3] .155		11.43	2.50	1.47	11o21°W	3].155°N	0.00	4.0-
PuantSul rceFarate:i&11o21,i3] .155		11.43	2.50	1.47	11o21°W	3].155°N	0.00	4.0-
PuantSul rceFarate:i811021,i3] .40]		14	2.05	1.42	11o21°W	3].40] °N	0.00	1.4]
PuantSul rceFarate:i811o21,i3].40]		14	2.05	1.42	11o21°W	3].40] °N	0.00	1.4]



No Address at This Location

ASCE Hazards Report

Standard: ASCE/SEI 7-16

Risk Category: II Soil Class: C

II C - Very Dense Soil and Soft Rock

Latitude: 34.086503 Longitude: -118.950182 Elevation: 983.2305421851612 ft (NAVD 88)





Site Soil Class: Results:	C - Very Dense	Soil and Soft Rock	
S _s :	1.471	S _{D1} :	0.511
S ₁ :	0.516	T∟ :	8
F _a :	1.2	PGA :	0.631
F _v :	1.484	PGA M :	0.758
S _{MS} :	1.765	F _{PGA} :	1.2
S _{M1} :	0.766	l _e :	1
S _{DS} :	1.177	C _v :	1.194
Sciemie Design MCER	Response Spectrum	12	Design Response Spectrum









SC6164 MP 2.96 U.S. Geological Survey - Earthquake Hazards Program

Unified Hazard Tool

Please do not use this tool to obtain ground motion parameter values for the design code reference documents covered by the <u>U.S. Seismic Design Maps web tools</u> (e.g., the International Building Code and the ASCE 7 or 41 Standard). The values returned by the two applications are not identical.

Please also see the new <u>USGS Earthquake Hazard Toolbox</u> for access to the most recent NSHMs for the conterminous U.S. and Hawaii.

∧ Input	
Edition	Spectral Period
Dynamic: Conterminous U.S. 2014 (Peak Ground Acceleration
Latitude	Time Horizon
Decimal degrees	Return period in years
34.065803	478
Longitude	
Decimal degrees, negative values for western longitudes	
-116.980162	
Site Class	
837 m/s (Site class C)	





Summary statistics for, Deaggregation: Total

Deaggregation targets	Recovered targets					
Return period: 475 yrs	Return period: 501.g9229 yrs					
Exceedance rate: 0.0021052632 yr ⁻¹ PGA ground motion: 0.377g1279 %	Exceedance rate: 0.0019924594 yr ⁻¹					
Totals	Mean (over all sources)					
Binned: 100 k	m: 6.55					
Residual: 0 k	r: 15.33 n8					
Trace: 0.1g k	ε ₀ : 0.73 σ					
Mode (largest m-r bin)	Mode (largest m-r-ε₀ bin)					
m: 6.11	m: 5.09					
r: g.4g m8	r: 6.g9 n8					
ε ₀ : 0.51 σ	ε ₀ : 1.2 σ					
Contribution: 7.75 k	Contribution: 2.97 k					
Discretization	Epsilon keys					
r: 8 in = 0.0, 8 ax = 1000.0, Δ = 20.0 n8	ε0: [-∞2.5)					
m: 8 in = 4.4, 8 ax = 9.4, ∆ = 0.2	ε1: [-2.52.0)					
ε: 8 in = -3.0, 8 ax = 3.0, Δ = 0.5 σ	ε2: [-2.01.5)					
	ε3: [-1.51.0)					
	ε4: [-1.00.5)					
	ε5: [-0.50.0)					
	ε6: [0.00.5)					
	ε7: [0.51.0)					
	ε8: [1.0., 1.5]					

ε10: [2.0..2.5) **ε11:** [2.5..+∞]

ε9: [1.5..2.0)

Deaggregation Contributors

Source Set 💪 Source	Туре	r	m	ε ₀	lon	lat	az	%
UC33brAvg_FM31	System							0.966
Malibu Coast alt 1 [.]		4921	2907	-8986	1179 33°W	349847°N	16.944	697(
Malibu Coast Exnte) sio) 5alt 1 [8]		39 2	(91.4	-8922	1179 64°W	349860°N	17492.	392(
A) acapa-Dume alt 1 [0]		18964	(980	-8961	1179.1°W	339 (2°N	1.290	0971
Simi-Sa) ta Rosa [6]		1(97((98.	89 0	1179°W	349041°N	346932	0928
Oak Ridge EO) shore5[8]		049 8	(963	897(11.9106°W	34902. °N	3019(6	19(7
Sisar [1]		1.970	(927	8930	11. 982. °W	349487°N	3409.	196.
Sa) Pedro Basi) [11]		01962	2976	1942	1179(.(°W	339 41°N	137974	1910
Oak Ridge ED) shore5[3]		0.936	(96(1987	1179 0. °W	349320°N	3967	1911
UC33brAvg_FM30	System							0497(
A) acapa-Dume alt 0 [6]	-	18970	(906	-893	1179.7°W	339 (4°N	1987	39 0
Malibu Coast Exnte) sio) 5alt 0 [8]		39.	(96(-89 2	1179 64°W	349864°N	176923	3906
Simi-Sa) ta Rosa [6]		1(97((986	89 6	1179°W	349041°N	346932	0941
Malibu Coast alt 0 [4]		4921	297.	-8964	1179 33°W	349861°N	167981	19 2
Oak Ridge ED) shore5[8]		049 8	(942	89 2	11. 9106°W	34902. °N	3019(6	1922
Sisar [1]		1.970	(924	893(11. 982. °W	349487°N	3409.	1930
UC33brAvg_FM31 Eopt5	Grid							03988
Poi) tSourceFi) ite: -1179 68, 34910(29((6924	8923	1179 68°W	3491.0(°N	8988	2986
Poi) tSourceFi) ite: -1179 68, 34910(29((6924	8923	1179 68°W	3491.0(°N	8988	2986
Poi) tSourceFi) ite: -1179 68, 349171		11986	69(4	1901	1179 68°W	349171°N	8988	1973
Poi) tSourceFi) ite: -1179 68, 349171		11986	69(4	1901	1179 68°W	349171°N	8988	1973
Poi) tSourceFi) ite: -1179 68, 349087		10972	69 (1902	1179 68°W	349087°N	8988	19(4
Poi) tSourceFi) ite: -1179 68, 349087		10972	69 (1902	1179 68°W	349087°N	8988	19(4
UC33brAvg FM30 Ept5	Grid							0096.
Poi) tSourceFi) ite: -1179 68, 34910(29 2	6922	8928	1179 68°W	34910(°N	8988	6927
Poi) tSourceFi) ite: -1179 68. 34910(292	6922	8928	1179 68°W	34910(°N	8988	6927
Poi) tSourceFi) ite: -1179 68, 349171		11903	69(8	190(1179 68°W	349171°N	8988	0983
Poi) tSourceFi) ite: -1179 68, 349171		11903	69 8	190(1179 68°W	349171°N	8988	0983
Poi) tSourceFi) ite: -1179 68, 349087		10976	69 7	1902	1179 68°W	349087°N	8988	193
Poi) tSourceFi) ite: -1179 68, 349087		10976	69 7	1902	1179 68°W	349087°N	8988	19(3